

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002821/AYA3Q2**Date:** 13/03/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100493796
Claimant Vehicle No :	SME862Z	Insured Vehicle No :	SLG6113P
Date of Loss:	24/03/2022	Nature of Claim:	TP
		Claim No:	3669475309SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME862Z	Engine No:	2AZC471330
Make & Model:	TOYOTA ESTIMA, 2.4 E X (A)	Chassis No:	ACR500077778
Reg. Date:	19/09/2008 (Man. Year: 2008)	Odometer:	157065 km
Colour:	Black		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,451.05	4,475.25	7,975.80	64.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,950.00	1,270.00	2,680.00	67.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,401.05	5,745.25	10,655.80	64.97
Approved Total (Overridden) (S\$)		4,600.00		
Nett Amount (S\$)	16,401.05	4,600.00	11,801.05	71.95
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,107.45		

INSPECTION

Date of Assignment:	25/03/2022	
Date Inspected:	25/03/2022	Inspected At: Kt Motorwerk (HQ) Blk 3012 Bedok Industrial Park E, #01-2020 Singapore 489978
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	987.60 FL	*- FL
2	1		*BONNET INNER LOCK	Not Necessary	92.20 FL	*- FL
3	1		*BONNET LOCK CABLE	Not Necessary	65.50 FL	*- FL
4	1		*FRONT GRILLE	Cracked	609.80 FL	*481.00 FL
5	1		*FRONT GRILLE OUTER GARNISH	Not Necessary	292.10 FL	*- FL
6	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FL	*30.00 FL
7	1		*FRONT GRILLE TOP RUBBER	Not Necessary	86.20 FL	*- FL
8	1		*FRONT GRILLE BADGE	Necessary	95.60 FL	*95.60 FL
9	1		*HEADLAMP (HID)	O/S Cracked	2,371.20 FL	*1,185.60 FL
10	2		*SETS HEADLAMP CLIPS	Necessary	60.00 FL	*10.00 FL
11	1		*FRONT BUMPER	Deformed	1,793.80 FL	*861.00 FL
12	2		*FRONT BUMPER SIDE RETAINERS	Necessary	160.00 FL	*80.00 FL
13	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
14	1		*FRONT BUMPER REINFORCEMENT	Dented	387.50 FL	*387.50 FL
15	1		*FRONT BUMPER SPONGE	Cracked	186.20 FL	*186.20 FL
16	1		*FRONT BUMPER LOWER GRILLE	Deformed	287.60 FL	*182.00 FL
17	1		*FRONT BUMPER	Bent	197.70 FL	*197.70 FL
18	1		*FRONT BUMPER TOW COVER	Not Necessary	50.70 FL	*- FL
19	1		*FRONT BUMPER FOG LAMP	O/S Cracked	937.40 FL	*325.00 FL
20	1		*FRONT BUMPER FOG LAMP COVER	O/S Missing	193.60 FL	*96.80 FL
21	2		*FRONT BUMPER FOG LAMP BRACKET	Not Necessary	125.50 FL	*- FL
22	1		*FRONT BUMPER BOTTOM COVER	Torn	178.60 FL	*178.60 FL
23	1		*SET FRONT BUMPER BOTTOM COVER CLIPS	Necessary	30.00 FL	*30.00 FL
24	1		*SUPPORT PANEL	Not Necessary	897.50 FL	*- FL
25	1		*SUPPORT PANEL TOP GARNISH	Deformed	325.70 FL	*245.00 FL
26	1		*SET SUPPORT PANEL TOP GARNISH CLIPS	Necessary	40.00 FL	*20.00 FL
27	1		*RADIATOR	Not Necessary	2,059.80 FL	*- FL
28	1		*RADIATOR TOP GARNISH	Not Necessary	119.50 FL	*- FL
29	1		*AIR CON CONDENSER	Dented	1,860.60 FL	*1,345.00 FL
30	1		*CONDENSER AIR CON PIPE	Not Necessary	582.60 FL	*- FL
31	1		*CONDENSER SUCTION PIPE	Not Necessary	565.40 FL	*- FL
32	1		*CONDENSER DISCHARGE PIPE	Not Necessary	276.90 FL	*- FL
33	1		*CONDENSER SIDE AIR GUIDES	Not Necessary	98.60 FL	*- FL
34	1		*WIPER TANK	Not Necessary	157.30 FL	*- FL
35	1		*WIPER TANK NECK	Not Necessary	42.60 FL	*- FL
36	1		*WIPER TANK CAP	Not Necessary	30.20 FL	*- FL
37	1		*WIPER TANK MOTOR	Not Necessary	195.90 FL	*- FL
38	1		*SET RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	16,581.40	5,967.00
- List Item Discount on L Items 25.00/25.00% (S\$)	4,130.35	1,491.75
Total Parts (S\$)	12,451.05	4,475.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	600.00
2	SPRAY PAINTING	New	1,800.00	500.00
3	CHECK WIRING ON HEADLAMP AND FOCUSING	New	100.00	30.00
4	ANTI RUST	New	100.00	60.00
5	REMOVE AND INSTALL AIR CON	New	150.00	80.00
Gross Labour Cost (\$\$)			3,950.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >