



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 1762J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR FENDER R/H (CONSISTENT)	DENTED	600.25	600.25
1	FRONT FENDER INNER SHIELD (CONSISTENT)	NOT NECESSARY	238.75	-
1	FRONT HEADLAMP R/H (CONSISTENT)	CUT	2,148.75	2,148.75
1	FRONT BUMPER (CONSISTENT)	DEFORMED	846.50	846.50
1	FRONT BUMPER SIDE RETAINER (CONSISTENT)	NOT NECESSARY	58.70	-
1	SET FRONT BUMPER CLIP (CONSISTENT)	NECESSARY	68.00	30.00
	LESS 10% DISCOUNT		-	-362.55
			3,960.95	3,262.95
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT TYRE SPORT RIM (SN) (CONSISTENT)	CUT	749.50	500.00
			749.50	500.00
	<u>LABOUR</u>			
	LABOUR FOR KNOCKING CHASSIS FRAME, CUTTING, WELDING, REPAIRING AND REPLACEMENT OF PARTS.		800.00	400.00
	TO SPRAY PAINT ON THE AFFECTED PORTION.		800.00	400.00
	TO APPLY RUST-PROOFING.	NOT NECESSARY	100.00	-
	TO CHECK WIRING.		40.00	30.00
	TO REMOVE / RENEW HEADLAMP AND FOCUS THE ALIGNMENT.	NOT NECESSARY	120.00	-
			1,860.00	830.00
	GRAND TOTAL		6,570.45	4,592.95
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,600.00

Report Ref No. CS/ASM22002831/Aty3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.