

CHENG MOTOR WORK CO

1 KAKI BUKIT AVE.6 #01-83
SINGAPORE 417883
Tel:65551185/6 Fax:65551184
H/P: 96713335
E-mail:chengmotor27@yahoo.com

AXA Insurance Singapore Pte. Ltd
8 Shenton Way #27-01
AXA Tower
Singapore 068811
Attn: motor claims Dept

28/3/22

Estimate cost of repair vehicle no: SLE1762J

Front Fender R/h *Dented*
Front fender inner Shield *new*
Front headlamp R/h *cut*
Front bumper *Dented*
Front bumper side retainer *new*
1set Front bumper clip *new*
Front Tyre sport rim *cut*

\$600.25 ✓
238.75 +
2148.75 ✓
846.50 ✓
58.70 +
~~68.00~~ 30.
~~749.50~~ 500(SN).

Labour for knocking chassis frame, cutting, welding, repairing
And replacement of parts.
To spray paint on the affected portion.
To apply rust-proofing
To check wiring
To remove/renew Headlamp and Focus the alignment

~~800.00~~ 400
~~800.00~~ 400
100.00 +
~~40.00~~ 30.
~~120.00~~ X.

Adrian Lj
H/s 29/03/22
04 Days