

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 696G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CUT	2,312.20	1,900.00
1	REAR BUMPER DIFFUSAL	SCRATCHED	385.00	385.00
1	REAR BUMPER DIFFUSAL CHROME	SCRATCHED	399.30	325.00
2	REAR BUMPER RETAINER	SERVICEABLE	101.20	-
2	REAR BUMPER PDC SENSOR	CUT	675.40	500.00
1	REAR BUMPER INNER GUIDE	SERVICEABLE	255.20	-
1	REAR BUMPER REINFORCEMENT	DENTED	1,124.20	1,124.20
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	1,779.80	-
1	REAR EXHAUST SILENCER CHROME TIP	TO REPAIR SEE LABOUR	399.30	-
	LESS 10% DISCOUNT		-743.16	-423.42
			6,688.44	3,810.78
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	30.00	30.00
			30.00	30.00
	<u>LABOUR</u>			
	CHECK WIRING & LIGHTING SYSTEM.		60.00	30.00
	REMOVE & REPLACE REAR PDC SENSOR.		150.00	40.00
	REMOVE & REFIT TRIMS & GARNISHES FOR REPAIR.	NOT NECESSARY	150.00	-
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR EXHAUST SILENCER AND REAR EXHAUST SILENCER CHROME TIP.		800.00	300.00
	SPRAY PAINTING ON AFFECTED AREAS.		800.00	200.00
			1,960.00	570.00
	GRAND TOTAL		8,678.44	4,410.78



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	3,550.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/FCI22002840/Vqy3e2



THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.