



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 7531M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	DENTED	868.80	868.80
2	BONNET HINGE @\$51.10	NOT NECESSARY	102.20	-
1	BONNET SPONGE	NOT NECESSARY	390.50	-
1	BONNET EMBLEM	NECESSARY	58.50	58.50
2	HEAD LAMP @\$863.60	CRACKED	1,727.20	1,727.20
1	RADIATOR GRILLE	CRACKED	292.80	292.80
1	TOP PANEL GARNISH	DEFORMED	115.70	115.70
1	FRONT BUMPER	DEFORMED	679.40	584.00
2	BUMPER SIDE RETAINER @\$55.30	NOT NECESSARY	110.60	-
2	BUMPER BRACKET @\$42.90	NOT NECESSARY	85.80	-
1	LH BUMPER LOWER GRILLE COMPLETE	DEFORMED	167.30	167.30
1	BRACE PANEL	NOT NECESSARY	89.70	-
	LESS 25% DISCOUNT		-	-953.58
			4,688.50	2,860.72
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	40.00	-
1	SET CLIP BUMPER (ADDITIONAL)(SN)	NECESSARY	60.00	30.00
			100.00	30.00
	<u>LABOUR</u>			
	TO KNOCK AND REPAIR AFFECTED AREAS.		800.00	400.00
	TO CONDUCT WIRING CHECKS.		80.00	30.00
	SPRAY PAINTING ON ALL AFFECTED PARTS.		800.00	400.00
			1,680.00	830.00
	GRAND TOTAL		6,468.50	3,720.72
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,900.00

Report Ref No. CS/SMO22002842/Aty3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.