

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 7220Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	NUMBER PLATE TRIM (NPA) (SN)	NOT NECESSARY	-	-
1	EMBLEM - DISPATCH (NPA) (SN)	NOT NECESSARY	-	-
1	BADGE-E (NPA) (SN)	NOT NECESSARY	-	-
1	DOOR ADHESIVE TAPE (NPA) (SN)	NOT NECESSARY	-	-
1	70KM/H STICKER (SN)	NOT NECESSARY	120.00	-
1	6 PAX STICKER (SN)	NOT NECESSARY	80.00	-
1	RR NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	80.00	-
1	C&C BADGE (SN)	NOT NECESSARY	50.00	-
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
1	REAR BUMPER (SN)	BROKEN	1,023.00	1,023.00
1	BUMPER BRACKET (SN)	NOT NECESSARY	109.00	-
1	BUMPER BRACKET LH LAT (SN)	NOT NECESSARY	138.00	-
1	BUMPER BRACKET RH LAT (SN)	NOT NECESSARY	138.00	-
1	BUMPER BRACKET RH LAT (SN)	NOT NECESSARY	123.00	-
1	BUMPER BRACKET (SN)	NOT NECESSARY	605.00	-
1	BADGE-LOGO (SN)	NOT NECESSARY	58.00	-
			2,574.00	1,023.00
	<u>LABOUR</u>			
	RENEW RR BUMPER. REPAIR TAILGATE LH / RH.		3,040.00	760.00
	RESPRAY TAILGATE LH & RH.	NOT NECESSARY	1,100.00	-
	CHECK WIRING ELECTRICAL SYSTEM.		80.00	80.00
	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM.		300.00	300.00
	REMOVE & REFIT REVERSE SENSOR.		100.00	100.00
			4,620.00	1,240.00
	GRAND TOTAL		7,194.00	2,263.00



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 2,263.00

Report Ref No. CS/FCI22002844/Evy3e2



Automotive Assessor



**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser**