



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMY 6361H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,141.00	-
1	REAR BUMPER TOWING COVER	NOT NECESSARY	72.00	-
2	REAR BUMPER REFLECTOR LH & RH @\$74.20	NOT NECESSARY	148.40	-
1	REAR BUMPER LOWER GUARD	NOT NECESSARY	196.00	-
1	REAR BUMPER LOWER GUARD COVER	NOT NECESSARY	778.00	-
2	REAR BUMPER SIDE BRACKET	NOT NECESSARY	35.40	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	2,760.00	-
1	REAR FENDER GARNISH RH	TO REPAIR SEE LABOUR	220.00	-
1	REAR FENDER INNER SHIELD RH	NOT NECESSARY	210.00	-
1	REAR SHOCK ABSORBER RH	NOT NECESSARY	772.00	-
1	REAR LOWER ARM RH	NOT NECESSARY	860.00	-
1	REAR KNUCKLE ARM RH	NOT NECESSARY	1,160.00	-
1	REAR DOOR LOWER SKIRT	DEFORMED	628.00	628.00
	LESS 5% DISCOUNT		-449.04	-31.40
			8,531.76	596.60
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	100.00	-
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	550.00	-
1	REAR RIM RH (SN)	CUT	1,300.00	850.00
1	REAR TYRE RH (SN)	NOT NECESSARY	380.00	-
1	SET REAR FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	100.00	-
			2,430.00	850.00
<b><u>LABOUR</u></b>				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER,REAR FENDER RH AND REAR FENDER GARNISH RH .		1,600.00	200.00
	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED.		1,400.00	700.00

Report Ref No. CS/AGI22002845/Any3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REFIX WIRING SYSTEM AT ACCIDENT DAMAGE AREAS AND CHECK FOR PROPER FUNCTION .	NOT NECESSARY	150.00	-
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS .	NOT NECESSARY	100.00	-
	TO CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	150.00	-
	TO REMOVE REAR BOOT MECHANISM .	NOT NECESSARY	150.00	-
	TO REMOVE AND REPLACE UNDERCARRIAGE PART.	NOT NECESSARY	210.00	-
	TO CONDUCT WHEEL ALIGNMENT TEST.		150.00	80.00
	TO CLEAR FAULT CODE WITH DIAGNOSTIC COMPUTER AND RESET TO SPECIFICATION .	NOT NECESSARY	180.00	-
			4,090.00	980.00
<b>GRAND TOTAL</b>			<b>15,051.76</b>	<b>2,426.60</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,900.00</b>

Report Ref No. CS/AGI22002845/Any3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.