

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002846/EQY3M4**Date:** 17/06/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00049832100

Claimant Vehicle No : SKM8026A**Insured Vehicle No :** YQ4321L

Date of Loss: 23/03/2022

Nature of Claim: TP

Claim No: SNM22D202026/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKM8026A**

Make & Model: MERCEDES-BENZ E300E, 2.0 AVANTGARDE FL (A) Engine No: 27492032001110

Reg. Date: 17/01/2022 (Man. Year: 2021)

Chassis No: W1K2130532B009131

Colour: Black

Odometer: 7270 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/35 R19	Rear Tyre Size:	275/35 R19
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,537.88	5,257.57	280.31	5.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,100.00	3,060.00	1,040.00	25.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	9,637.88	8,317.57	1,320.31	13.70
+ GST 7.00/7.00% (\$\$)	674.65	582.23	92.42	13.70
Nett Amount (\$\$)	10,312.53	8,899.80	1,412.73	13.70

INSPECTION

Date of Assignment: 02/06/2022

Date Inspected: 10/05/2022 Inspected At:

Cycle & Carriage Industries Pte Ltd (Pandan Loop)
188 Pandan Loop
Singapore 128378

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Jun 2022)

Parts: 143 MERCEDES-BENZ E300E 2.0 AVANTGARDE FL (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKM8026A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LEFT HEADLAMP UNIT	Cut	3,538.41 FS	*3,619.80 FS
2	1		*FRONT BUMPER	Crushed	1,600.95 FS	*1,637.77 FS
3	1		*FRONT AIR DUCT SEGMENT	Not Necessary	141.17 FS	*- FS
4	1		*FRONT BUMPER LOWER CHROME TRIM	Not Necessary	188.52 FS	*- FS
5	1		*LEFT FRONT BASIC CARRIER FOR BUMPER	Not Necessary	68.83 FS	*- FS
Total Parts (S\$)						5,537.88
						5,257.57

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	New	1,200.00	960.00
2	RESPRAY BONNET AND FRONT BUMPER	New	2,400.00	1,600.00
3	USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS	New	380.00	380.00
4	CHECK HEADLAMP WITH FOCUS ADJUSTMENT	New	120.00	120.00
Gross Labour Cost (S\$)			4,100.00	3,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >