

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22002856/APA3Q2**Date:** 29/08/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MFL0003414_02
Claimant Vehicle No : SGZ6937M **Insured Vehicle No :** SMR3647R
 Date of Loss: 27/03/2022 Nature of Claim: TP Claim No: MFL2022D0001763

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGZ6937M**
 Make & Model: TOYOTA AXIO, 1.5 (A) Engine No: 1NZC734411
 Reg. Date: 13/11/2007 (Man. Year: 2007) Chassis No: NZE1416049961
 Colour: Grey Odometer: 243391 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,963.54	3,444.42	5,519.12	61.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	2,140.00	940.00	30.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,043.54	5,584.42	6,459.12	53.63
Approved Total (Overridden) (S\$)		3,300.00		
(S\$)	12,043.54	3,300.00	8,743.54	72.60
+ GST 7.00/7.00% (S\$)	843.05	231.00	612.05	72.60
Nett Amount (S\$)	12,886.59	3,531.00	9,355.59	72.60
+ Loss of Use (13.0 x S\$60.00/day) (S\$)		780.00		
+ Doc/Search Fee (S\$)		36.45		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		4,407.45		
Global Sum Settlement (S\$)		4,400.00		

INSPECTION

Date of Assignment: 28/03/2022
 Date Inspected: 28/03/2022 Inspected At: Ryder Auto Pte Ltd (HQ)
 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
 Singapore 417921
 Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Jul 2022)
Parts: 143	TOYOTA AXIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGZ6937M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	681.40 FL	*495.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	2		*REAR BUMPER SCREW CLIPS	Necessary	20.00 FS	*20.00 FS
4	2		*REAR BUMPER O/S & N/S REFLECTOR	Not Necessary	475.40 FL	*- FL
5	2		*REAR BUMPER O/S & N/S RETAINER	Necessary	362.70 FL	*70.00 FL
6	2		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
7	1		*REAR END PANEL	Dented	481.90 FL	*481.90 FL
8	1		*REAR END PANEL INNER TRIM	Deformed	453.50 FL	*200.00 FL
9	4		*REAR END PANEL INNER TRIM CLIPS	Necessary	16.00 FS	*16.00 FS
10	2		*REAR O/S & N/S TAIL LAMP	Cracked	878.20 FL	*642.00 FL
11	2		*REAR O/S & N/S TAIL LAMP PANEL	Repair	563.80 FL	*- FL
12	2		*REAR O/S & N/S TAIL LAMP SEALANT	Not Necessary	100.00 FL	*- FL
13	1		*REAR REGN NO PLATE LAMP	Not Necessary	167.50 FL	*- FL
14	1		*REAR BOOT COVER	Buckled	874.40 FL	*874.40 FL
15	1		*REAR BOOT COVER WEATHERSTRIP	Cut	124.40 FL	*124.40 FL
16	1		*REAR BOOT COVER EMBLEM	Necessary	61.50 FL	*61.50 FL
17	1		*REAR BOOT COVER AXIO EMBLEM	Necessary	61.70 FL	*61.70 FL
18	1		*REAR BOOT COVER X EMBLEM	Necessary	67.70 FL	*67.70 FL
19	1		*REAR BOOT COVER INNER TRIM	Not Necessary	282.25 FL	*- FL
20	11		*REAR BOOT COVER INNER TRIM CLIPS	Not Necessary	33.00 FS	*- FS
21	2		*REAR BOOT COVER O/S & N/S HINGES	Not Necessary	164.50 FL	*- FL
22	1		*REAR BOOT COVER MOULDING	Not Necessary	187.10 FL	*- FL
23	4		*REAR BOOT COVER MOULDING CLIPS	Not Necessary	16.00 FS	*- FS
24	1		*REAR BOOT COVER LOCK (UPPER)	Damaged	191.60 FL	*191.60 FL
25	1		*FRONT BUMPER	Deformed	796.70 FL	*485.00 FL
26	10		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
27	1		*FRONT BUMPER INSULATOR	Not Necessary	394.20 FL	*- FL
28	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	596.70 FL	*- FL
29	2		*FRONT BUMPER O/S & N/S RETAINER	Not Necessary	386.70 FL	*- FL
30	1		*FRONT BUMPER GRILLE (LOWER)	Not Necessary	496.60 FL	*- FL
31	1		*FRONT BUMPER ENFORCEMENT COVER	Not Necessary	206.70 FL	*- FL
32	1		*FRONT GRILLE	Cracked	436.70 FL	*347.00 FL
33	1		*FRONT GRILLE EMBLEM	Necessary	71.70 FL	*71.70 FL
34	6		*FRONT GRILLE CLIPS	Necessary	18.00 FS	*18.00 FS
35	1		*FRONT BONNET	Not Necessary	799.70 FL	*- FL
36	1		*FRONT O/S & N/S HEAD LAMP	Not Necessary	896.80 FL	*- FL
37	1		*FRONT REG.NO PLATE	Not Necessary	45.00 FS	*- FS
38	1		*FRONT REG.NO PLATE BRACKET	Not Necessary	29.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,779.05	4,487.90
- List Item Discount on L Items 25.00/25.00% (\$)	2,815.51	1,043.48
Total Parts (\$)	8,963.54	3,444.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING	New	1,400.00	1,000.00
2	TO SPRAY PAINTING	New	1,200.00	1,000.00
3	TO REMOVE & REPLACE REAR EXHAUST	New	100.00	0.00
4	TO RESET ELECTRICAL SYSTEM	New	180.00	0.00
5	TO CHECK WIRING	New	100.00	60.00
6	TO RESEAL ANTI RUST	New	100.00	80.00
Gross Labour Cost (\$)			3,080.00	2,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >