

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22002857/VGA3Q2**Date:** 19/07/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0005664
Claimant Vehicle No : JQG8893 **Insured Vehicle No :** YM7053L
 Date of Loss: 27/01/2021 Nature of Claim: TP Claim No: MFL2021D0000509

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **JQG8893**
 Make & Model: KAWASAKI EX250-L, 249cc Engine No: EX250LEC06463
 Reg. Date: 01/01/2014 (Man. Year: 2014) Chassis No: PNKEX250LLMC57176
 Colour: Green Odometer: 0 km
 Engine Capacity: 249 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70 R17 Rear Tyre Size: 110/70 R17
 Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,390.00	12,453.90	12,936.10	50.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,020.00	370.00	650.00	63.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	26,410.00	12,823.90	13,586.10	51.44
Approved Total (Overridden) (\$\$)		1,600.00		
Nett Amount (\$\$)	26,410.00	1,600.00	24,810.00	93.94
+ Other Costs (\$\$)		50.00		
Nett Liability (\$\$)		1,650.00		

INSPECTION

Date of Assignment: 28/03/2022
 Date Inspected: 29/03/2022 Inspected At: Sanfu Motor Pte Ltd (Kaki Bukit)
 1 Kaki Bukit Ave 6, #02-43 Autobay @ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 0.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

BOOK VALUE : \$5,000.00

LTA REIMBURSEMENT VALUE (RV) : \$3,400.00

NETT VALUE : \$1,600.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 02 Jun 2022)	
Parts:	N/A	KAWASAKI EX250-L 249cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JQG8893)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD COWLING	Bent	353.00 F	*353.00 FL
2	1		*HEADLIGHT	Missing	1,391.00 F	*1,391.00 FL
3	1		*HEADLIGHT BRACKET	Bent	642.00 F	*642.00 FL
4	1		*FRONT FORK (L&R SET)	*Check	3,852.00 F	*- FL
5	1		*STEERING STEM	*Check	738.00 F	*- FL
6	1		*FRONT FENDER	Cut	417.00 F	*417.00 FL
7	1		*FRONT RIM	*Check	1,766.00 F	*- FL
8	1		*RADIATOR	*Check	1,316.00 F	*- FL
9	1		*LH RADIATOR INNER PANEL	*Check	193.00 F	*- FL
10	1		*RH RADIATOR INNER PANEL	*Check	193.00 F	*- FL
11	1		*INNER FENDER	*Check	193.00 F	*- FL
12	1		*L&R HANDLE BAR	*Check	449.00 F	*- FL
13	1		*L&R LEVER	Scratched	161.00 F	*161.00 FL
14	1		*L&R GRIPS	Scratched	98.00 F	*98.00 FL
15	1		*L&R BAR END	Scratched	98.00 F	*98.00 FL
16	1		*L&R MIRROR	Missing	471.00 F	*471.00 FL
17	1		*REFTIFIER	*Check	770.00 F	*- FL
18	1		*FRONT L&R SIGNAL LIGHTS	Cracked	289.00 F	*289.00 FL
19	1		*SPEEDOMETER	Missing	1,830.00 F	*1,830.00 FL
20	1		*FRONT LH COWLING	Cut	1,284.00 F	*1,284.00 FL
21	1		*RH ENGINE CASING	Cut	385.00 F	*385.00 FL
22	1		*RH RIDER FOOTREST PEG	Scratched	225.00 F	*225.00 FL
23	1		*RH BRAKE PEDAL	Scratched	129.00 F	*129.00 FL
24	1		*RH PILLION FOOTREST PEG	Scratched	118.00 F	*118.00 FL
25	1		*EXHAUST MUFFLER	Scratched	1,926.00 F	*1,926.00 FL
26	1		*RH TAIL COWLING	Serviceable	161.00 F	*- FL
27	1		*LH TAIL COWLING	Serviceable	161.00 F	*- FL
28	1		*REAR FENDER	Serviceable	140.00 F	*- FL
29	1		*RER LH SIGNAL LIGHT	Serviceable	129.00 F	*- FL
30	1		*REAR SIGNAL LIGHT BRACKET	Serviceable	128.00 F	*- FL
31	1		*PILLION SEAT	Serviceable	482.00 F	*- FL
32	1		*LH PILLION FOOTREST PEG	Serviceable	118.00 F	*- FL
33	1		*LH RIDER FOOTREST PEG	Scratched	225.00 F	*225.00 FL
34	1		*LH GEAR PEDAL	Scratched	118.00 F	*118.00 FL
35	1		*GHAIN	Distorted	240.00 F	*240.00 FL
36	1		*SPROCKET	*Check	260.00 F	*- FL
37	1		*REAR RIM SLIDER	*Check	128.00 F	*- FL
38	1		*RH BELLY COWLING	*Check	161.00 F	*- FL
39	1		*LH BELLY COWLING	*Check	161.00 F	*- FL
40	1		*FUEL TANK	Dented	2,087.00 F	*2,087.00 FL
41	1		*FRONT RH COWLING 1	Bent	1,284.00 F	*1,284.00 FL
42	1		*STEERING CONE & BEARING	Missing	120.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,390.00	13,831.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,377.10

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					25,390.00	12,453.90
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	FRONT FORK ALIGNMENT	New	220.00	50.00
2	WHEEL ALIGNMENT	New	120.00	50.00
3	FRAME ALIGNMENT	New	200.00	70.00
4	WORKMANSHIP TO RENEW DAMAGE PARTS & AREAS	New	480.00	200.00
Gross Labour Cost (\$\$)			1,020.00	370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >