

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI22002858/TVY3E2

Date: 20/05/2022

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000206		
Claimant Vehicle No :	SHB2180U	Insured Vehicle No :	SLN7531Y		
Date of Loss:	25/03/2022	Nature of Claim:	TP	Claim No:	M2201419

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB2180U	Engine No:	G4LEKU385158
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU182953
Reg. Date:	14/11/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Yellow		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,123.92	709.28	1,414.64	66.61
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,030.00	1,180.00	850.00	41.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,164.92	1,900.28	2,264.64	54.37
+ GST 7.00/7.00% (S\$)	291.54	133.02	158.52	54.37
Nett Amount (S\$)	4,456.46	2,033.30	2,423.16	54.37

INSPECTION

Date of Assignment:	28/03/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	28/03/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 May 2022)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB2180U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Torn	459.40 FL	-	*459.40 FL
2	1		*REAR BUMPER BRACKET LH	Deformed	55.80 FL	-	*55.80 FL
3	1		*REAR WHEEL COVER LH	Cut	346.40 FL	-	*346.40 FL
4	1		*REAR FENDER LH	Repair	1,768.30 FL	-	*- FL
5	1		*PETROL STICKER	Necessary	20.00 FS	-	*20.00 FS
					Sub Total (S\$)	2,649.90	881.60
					- List Item Discount on L Items 20.00/20.00% (S\$)	525.98	172.32
					Total Parts (S\$)	2,123.92	709.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,250.00	560.00
2	SPRAY PAINTING	New	600.00	500.00
3	REMOVE/ REFIX REVERSE SENSOR	New	60.00	30.00
4	REMOVE/ REFIX UPHOLSTER REAR	New	60.00	60.00
5	TUFF COATING	New	60.00	30.00
Gross Labour Cost (\$\$)			2,030.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >