



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 6358E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR EXHAUST PIPE (CONSISTENT)	TO REPAIR SEE LABOUR	585.00	-
1	REAR EXHAUST PIPE PROTECTOR (FRONT) (CONSISTENT)	NECESSARY	85.00	85.00
1	REAR EXHAUST PIPE PROTECTOR (CENTRE) (CONSISTENT)	NECESSARY	128.00	128.00
1	REAR EXHAUST PIPE PROTECTOR (REAR) (CONSISTENT)	NECESSARY	75.00	75.00
1	FRONT WINDSHIELD (CONSISTENT)	CUT	165.00	165.00
1	BALANCER LH (CONSISTENT)	CUT	35.00	35.00
1	WING MIRROR LH (CONSISTENT)	CUT	70.00	70.00
1	REAR FAIRING LH (CONSISTENT)	CUT	295.00	295.00
1	REAR FAIRING EMBLEM LH (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR ENGINE COVER LH (CONSISTENT)	NECESSARY	268.00	268.00
1	REAR ENGINE COVER (HONDA) (CONSISTENT)	NECESSARY	245.00	245.00
1	MAIN STAND (CONSISTENT)	CUT	125.00	125.00
	LESS 10% DISCOUNT		-	-154.10
			2,126.00	1,386.90
<u>SPECIAL NETT ITEMS</u>				
2	REAR SLIDER @ \$80.00 (SN) (CONSISTENT)	CUT	160.00	160.00
2	REAR SLIDER BRACKET @ \$45.00 (SN) (CONSISTENT)	BENT	90.00	90.00
2	GUARD RAIL @ \$350.00 (SN) (CONSISTENT)	CUT	700.00	600.00
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	NECESSARY	15.00	15.00
1	GUARD RAIL STOPPER LH (SN) (CONSISTENT)	CUT	50.00	50.00
1	REAR BOX (SN) (CONSISTENT)	CUT	350.00	250.00
1	REAR BOX BRACKET (SN) (CONSISTENT)	NOT NECESSARY	200.00	-
1	FOOD DELIVERRY CONTAINER (SN) (CONSISTENT)	NOT NECESSARY	250.00	-
			1,815.00	1,165.00
<u>LABOUR</u>				
	LABOUR. INCLUSIVE OF THE REPAIR OF REAR EXHAUST PIPE.		400.00	200.00
	SPRAY PAINTING.		400.00	200.00

Report Ref No. CS/ASM22002859/Avy3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING.		50.00	30.00
	TO REMOVE EXHAUST PIPE.		60.00	40.00
	TOWING FEES.		40.00	40.00
			950.00	510.00
GRAND TOTAL			4,891.00	3,061.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CS/ASM22002859/Avy3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.