

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: S1M03OIR Date: 11<sup>th</sup> Apr 2022

Our Ref: CS3/ASM21012747/Evy3e2-1

## M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01 Axa Tower Singapore 068811 (The Motor Claims Department)

Attn: Ho Winnie

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJX 5069A INSURED VEHICLE: SJA 9916A

**ACCIDENT DATE: 13/12/2021** 

We thank you for your instruction on 29/03/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJX 5069A from M/s Impact Analysis Consultant.
- b) Singapore Accident Statement of Vehicle SJX 5069A and SJA 9916A.
- c) Police Report of Vehicle SJX 5069A.
- d) Final Repair Bill of SJX 5069A from M/s Perfect Power Pte Ltd.
- e) Colour damaged vehicle photographs of SJX 5069A.

Pre-Repair Inspection Date: 17/12/2021 at M/s Perfect Power Pte Ltd, 1 Bukit Batok Crescent #05-36, Weege Plaza, Singapore 658064.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SJX 5069A

Make & Model : Honda Civic IMA 1.3L CVT

Year of Registration : 2010

Chassis Number : JHMFD36209S205325

Engine Capacity : 1339 cc

- 2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.