

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002869/BGA3Q2**Date:** 19/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100493044
Claimant Vehicle No :	SLW1373D	Insured Vehicle No :	GBF5269D
Date of Loss:	28/03/2022	Nature of Claim:	TP
		Claim No:	3403906674SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW1373D	Engine No:	27091031507557
Make & Model:	MERCEDES-BENZ CLA180, 1.6 AMG (A)	Chassis No:	WDD1173422N607642
Reg. Date:	30/01/2018 (Man. Year: 2017)	Odometer:	73053 km
Colour:	Grey		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35 R19	Rear Tyre Size:	235/35 R19
Front Left Side:	Falken 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,485.84	5,674.17	8,811.67	60.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,350.00	1,660.00	2,690.00	61.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,835.84	7,334.17	11,501.67	61.06
Approved Total (Overridden) (S\$)		5,850.00		
(S\$)	18,835.84	5,850.00	12,985.84	68.94
+ GST 7.00/7.00% (S\$)	1,318.51	409.50	909.01	68.94
Nett Amount (S\$)	20,154.35	6,259.50	13,894.85	68.94
+ Car Rental (8.0 x S\$100.00/day + 7.00% GST) (S\$)		856.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,122.95		
Global Sum Settlement (S\$)		7,100.00		

INSPECTION

Date of Assignment:	30/03/2022	Team Autopro Pte Ltd (sin Ming) (HQ)
Date Inspected:	30/03/2022 Inspected At:	160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY
Estimated Period of Repair:	6.0 days	Singapore 575722

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,987.90 FL	*1,875.00 FL
2	1		*BOOTLID LOGO	Necessary	110.00 FL	*68.00 FL
3	1		*BOOTLID EMBLEM CLA250	Necessary	148.00 FL	*87.00 FL
4	1		*BOOTLID WEATHERSTRIP	Not Necessary	468.00 FL	*- FL
5	1		*BOOTLID INNER LOCK ASSY	Not Necessary	574.00 FL	*- FL
6	1		*BOOTLID OUTER GARNISH	Not Necessary	382.60 FL	*- FL
7	1		*REAR BUMPER	Broken	1,886.00 FL	*1,438.00 FL
8	1		*REAR BUMPER LOWER	Broken	686.30 FL	*368.00 FL
9	1		*REAR BUMPER LOWER CENTER GARNIS H	Broken	275.30 FL	*275.30 FL
10	1		*REAR BUMPER REINFORCEMENT	Dented	698.00 FL	*480.00 FL
11	1		*REAR BUMPER CENTRE BEAM GARNISH	Not Necessary	213.90 FL	*- FL
12	1		*REAR BUMPER REVERSE SENSOR (6 PCS)	Scratched (2 PCS ONLY)	1,590.00 FL	*290.00 FL
13	1		*REAR BUMPER TOW CAP	Not Necessary	125.00 FL	*- FL
14	1		*REAR END PANEL OUTER	Dented	1,125.00 FL	*980.00 FL
15	1		*REAR END PANEL INNER	Not Damaged	995.00 FL	*- FL
16	1		*REAR END PANEL TOP GARNISH	Not Damaged	415.00 FL	*- FL
17	2		*TAILLAMP	Not Damaged	1,460.00 FL	*- FL
18	2		*TAILLAMP BRACKET	Not Damaged	218.00 FL	*- FL
19	2		*REAR EXHAUST PIPE CHROME TIP	Not Damaged	690.00 FL	*- FL
20	1		*REAR EXHAUST PIPE HEAT SHIELD	Not Damaged	181.60 FL	*- FL
21	1		*REAR BUMPER HEAT SHIELD	Not Necessary	288.00 FL	*- FL
22	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
23	1		*BOOTLID SEALANT	Necessary	100.00 FS	*30.00 FS
24	1		*BOOTLID INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
25	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
26	1		*REAR BUMPER LOWER CLIPS	Necessary	60.00 FS	*30.00 FS
27	2		*REAR BUMPER SIDE RETAINER	Necessary	312.00 FS	*96.00 FS
28	6		*REAR BUMPER REVERSE SENSOR SEAL	Necessary	348.00 FS	*153.00 FS
29	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
30	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
31	2		*TAILLAMP CLIPS	Not Necessary	120.00 FS	*- FS
32	2		*TAILLAMP SEAL	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **15,937.60** **6,260.30**
- List Item Discount on L Items 10.00/10.00% (\$\$) 1,451.76 586.13

Total Parts (\$\$) **14,485.84** **5,674.17**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R BOOTLID COMPONENT	New	150.00	80.00
2	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
3	DIAGNOSTIC RESET FAULT CODE	New	300.00	120.00
4	CHECK WIRING	New	100.00	0.00
5	UPHOLSTERY	New	300.00	0.00
6	PANEL BEATING	New	1,600.00	800.00
7	RUST PROOFING	New	200.00	0.00
8	SPRAY PAINTING	New	1,600.00	600.00
Gross Labour Cost (\$\$)			4,350.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >