

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG22002876/KGA3Q2**Date:** 17/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700071308
<b>Claimant Vehicle No :</b>	SHD9804Y	<b>Insured Vehicle No :</b>	SJM2164K
Date of Loss:	25/03/2022	Nature of Claim:	TP
		Claim No:	5731895837SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD9804Y</b>		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2H05410
Reg. Date:	14/05/2021 (Man. Year: 2020)	Chassis No:	JTDKB3FU903092321
Colour:	Metallic Pearl White/Red	Odometer:	81662 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 9 mm	Rear Left Side:	Firenza 8 mm
Front Right Side:	Firenza 9 mm	Rear Right Side:	Firenza 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,973.65	1,546.20	7,427.45	82.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,300.00	910.00	8,390.00	90.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>18,273.65</b>	<b>2,456.20</b>	<b>15,817.45</b>	<b>86.56</b>
<b>+ GST 7.00/7.00% (S\$)</b>	1,279.16	171.93	1,107.23	86.56
<b>Nett Amount (S\$)</b>	<b>19,552.81</b>	<b>2,628.13</b>	<b>16,924.68</b>	<b>86.56</b>
<b>+ Loss of Use (6.0 x S\$50.00/day) (S\$)</b>		300.00		
<b>+ Car Rental (6.0 x S\$96.30/day) (S\$)</b>		577.80		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,513.38</b>		

INSPECTION

Date of Assignment:	28/03/2022		
Date Inspected:	28/03/2022	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	3.0 days		

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Buckled	485.60 FL	*485.60 FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Bent	332.70 FL	*332.70 FL
3	1		*COVER ,REAR BUMPER ,LOWER	Dented	22.00 FL	*22.00 FL
4	1		*GUARD ,REAR BUMPER ,CENTER	Dented / Cut	374.50 FL	*374.50 FL
5	1		*RETAINER ,REAR BUMPER SIDE ,LH	Serviceable	132.60 FL	*- FL
6	1		*RETAINER ,REAR BUMPER SIDE ,RH	Serviceable	132.60 FL	*- FL
7	1		*LENS & BODY ,REAR COMBINATION LAMP, RH	Serviceable	339.60 FL	*- FL
8	1		*LENS & BODY ,REAR COMBINATION LAMP,NO.2 RH	Serviceable	261.00 FL	*- FL
9	1		*PANEL SUB-ASSY ,BACK DOOR	Repair	1,147.80 FL	*- FL
10	1		*PLATE ,LUGGAGE COMPARTMENT DOOR NAME NO.2	Not Necessary	54.60 FL	*- FL
11	1		*PLATE BACK DOOR NAME NO.1	Not Necessary	54.60 FL	*- FL
12	1		*ORNAMENT SUB-ASSY ,BACK DOOR	Not Necessary	47.90 FL	*- FL
13	1		*GARNISH SUB-ASSY ,BACK DOOR OUTSIDE	Serviceable	913.60 FL	*- FL
14	1		*WEATHERSTRIP ,BACK DOOR	Serviceable	372.30 FL	*- FL
15	1		*COVER ,FLOOR UNDER NO.1 LH	Serviceable	175.10 FL	*- FL
16	1		*COVER ,FLOOR UNDER NO.2 RH	Serviceable	241.90 FL	*- FL
17	1		*COVER ,REAR FLOOR CTR	Serviceable	229.90 FL	*- FL
18	1		*COVER ,DECK TRIM REAR	Serviceable	126.70 FL	*- FL
19	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	651.00 FL	*- FL
20	1		*STAY ASSY ,BACK DOOR ,LH	Serviceable	242.50 FL	*- FL
21	1		*STAY ASSY ,BACK DOOR ,RH	Serviceable	242.50 FL	*- FL
22	1		*HINGE ASSY ,BACK DOOR ,LH	Repair	61.00 FL	*- FL
23	1		*HINGE ASSY ,BACK DOOR ,RH	Repair	61.00 FL	*- FL
24	1		*COVER ,FRONT BUMPER	Buckled	521.00 FL	*521.00 FL
25	1		*BRACKET ,FRONT BUMPER EXTENSION MOUNTING	Serviceable	110.50 FL	*- FL
26	1		*REINFORCEMENT SUB-ASSY ,FRONT BUMPER	Repair	716.60 FL	*- FL
27	1		*ABSORBER ,FRONT BUMPER ENERGY	Serviceable	80.20 FL	*- FL
28	1		*GRILLE SUB-ASSY ,RADIATOR	Serviceable	422.50 FL	*- FL
29	1		*GRILLE RADIATOR LOWER NO.1	Serviceable	178.60 FL	*- FL
30	1		*EMBLEM ASSY ,RADIATOR GRILLE	Cracked	105.80 FL	*105.80 FL
31	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
32	1		*SET REAR BUMPER CLIP	Necessary	95.00 FS	*60.00 FS
33	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
34	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
35	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS
36	1		*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
37	1		*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
38	1		*REAR BUMPER PROTECTOR	Not Necessary	180.00 FS	*- FS
39	1		*SET REAR BUMPER RETAINER CLIP	Not Necessary	85.00 FS	*- FS
40	1		*END PANEL TRIM CLIP	Not Necessary	65.00 FS	*- FS
41	1		*SET BUMPER CLIP FRT	Necessary	95.00 FS	*60.00 FS
42	1		*FRONT NUMBER PLATE WITH MOULDING	Bent	200.00 FS	*45.00 FS
43	1		*REAR NUMBER PLATE WITH MOULDING	Serviceable	200.00 FS	*- FS
44	1		*SET FRONT BUMPER RETAINER CLIP	Not Necessary	85.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>11,183.20</b>	<b>2,006.60</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	2,209.55	460.40
<b>Total Parts (\$)</b>	<b>8,973.65</b>	<b>1,546.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,200.00	400.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
5	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	0.00
6	TO REMOVE AND REFIT ELECTRICAL WIRING BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
7	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
8	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT VACUUM AND CHARGE-IN-GAS	New	380.00	0.00
9	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO RUST -PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
12	TOWING FEES	New	150.00	0.00
13	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	440.00
14	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
15	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
16	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
17	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	220.00	0.00
18	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>9,300.00</b>	<b>910.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >