

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002887/UVY3Q2**Date:** 26/05/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00139292100

Claimant Vehicle No : SND7849K**Insured Vehicle No :** XE5948Y

Date of Loss: 24/03/2022

Nature of Claim: TP

Claim No: SNM22D202069/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SND7849K**

Make & Model: HONDA CIVIC, 1.5 (A)

Engine No: R16B25502374

Reg. Date: 12/12/2018 (Man. Year: 2018)

Chassis No: MRHFC5650JT002049

Colour: Red

Odometer: 47581 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R16

Rear Tyre Size: 215/55 R16

Front Left Side: Yokohama 8 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,634.99	5,785.08	849.91	12.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	21,390.00	16,035.00	5,355.00	25.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	28,024.99	21,820.08	6,204.91	22.14
+ GST 7.00/7.00% (S\$)	1,961.75	1,527.41	434.34	22.14
Nett Amount (S\$)	29,986.74	23,347.49	6,639.25	22.14

INSPECTION

Date of Assignment: 28/03/2022

Date Inspected: 29/03/2022

Inspected At:

Kah Motor Co Sdn Bhd (Ubi)
15 Ubi Road 4
Singapore 408610

Estimated Period of Repair: 18.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 May 2022)
Parts:	143	HONDA CIVIC 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SND7849K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE ASSY ,RR BUMPER	Distorted	462.90 FS	*462.90 FS
2	1		*BEAM COMPRR BUMPER	Distorted	141.00 FS	*141.00 FS
3	1		*GARNISH ,RR.BUMPER LOWER	Torn	31.20 FS	*31.20 FS
4	1		*GARNISH ,R,RR.BUMPER SIDE	Cut	6.67 FS	*6.67 FS
5	1		*GARNISH ,L,RR.BUMPER SIDE	Cut	6.67 FS	*6.67 FS
6	1		*BRACKETR.RR.BUMPER SIDE	Bent	1.95 FS	*1.95 FS
7	1		*BRACKETL.RR.BUMPER SIDE	Bent	1.95 FS	*1.95 FS
8	1		*SPACERR.RR.BUMPER SIDE	Bent	8.62 FS	*8.62 FS
9	1		*SPACERL.RR.BUMPER SIDE	Bent	8.62 FS	*8.62 FS
10	1		*CLIP BUMPER (7 PCS)	Necessary	12.07 FS	*12.07 FS
11	1		*REFLECTOR ASSYR.RR	Not Necessary	6.15 FS	*- FS
12	1		*REFLECTOR ASSYL.RR	Not Necessary	6.15 FS	*- FS
13	1		*PANEL SETRR	Badly Dented	208.12 FS	*208.12 FS
14	1		*STIFFENER ,R.RR. PANEL SIDE	Bent	22.87 FS	*22.87 FS
15	1		*STIFFENERL.RR. PANEL SIDE	Bent	22.87 FS	*22.87 FS
16	1		*FAN COMPSPARE TIRE	Buckled	185.47 FS	*185.47 FS
17	1		*PANEL SETR.RR.OUTSIDE	Badly Dented	609.22 FS	*609.22 FS
18	1		*PANEL SETL.RR.OUTSIDE	Badly Dented / Cracked	609.22 FS	*609.22 FS
19	1		*GUTTERR.RR UPPER	Dented	25.12 FS	*25.12 FS
20	1		*GUTTERL.RR.UPPER	Dented	25.12 FS	*25.12 FS
21	1		*ADAPTERR.RR.COMBINATION LIGHT	Cracked	51.97 FS	*51.97 FS
22	1		*ADAPTERL.RR.COMBINATION LIGHT	Cracked	51.97 FS	*51.97 FS
23	1		*LID COMP TRUNK	Buckled	416.17 FS	*416.17 FS
24	1		*WEATHERSTRIPTRUNK LID	Twisted	52.50 FS	*52.50 FS
25	1		*GARNISH ASSYRR.LICENSE	Twisted	86.10 FS	*86.10 FS
26	1		*EMBLEM ,H -MARK	Necessary	10.50 FS	*10.50 FS
27	1		*NUT ,PUSH 3MM (2 PCS)	Necessary	3.15 FS	*3.15 FS
28	1		*LOCK ASSYTRUNK	Bent	63.67 FS	*63.67 FS
29	1		*LINING ASSYRR PANEL	Twisted	37.72 FS	*37.72 FS
30	1		*LINING ASSYTRUNK LID	Distorted	28.20 FS	*28.20 FS
31	1		*HINGE COMPR TRUNK	Bent	38.32 FS	*38.32 FS
32	1		*HINGE COMPL TRUNK	Bent	38.32 FS	*38.32 FS
33	1		*GARNISH ASSYR.TRUNK HINGE	Not Necessary	13.12 FS	*- FS
34	1		*GARNISH ASSYL.TRUNK HINGE	Not Necessary	13.12 FS	*- FS
35	1		*LID ASSYSPARE TIRE	Not Necessary	51.52 FS	*- FS
36	1		*BOX COMPTOOL	Not Necessary	32.55 FS	*- FS
37	1		*EMBLEM SETRR	Necessary	10.05 FS	*10.05 FS
38	1		*EMBLEMRR	Necessary	9.37 FS	*9.37 FS
39	1		*GLASS ASSYR ,QUARTER WINDSHIELD	Necessary	116.92 FS	*116.92 FS
40	1		*GLASS ASSYL ,QUARTER WINDSHIELD	Necessary	116.92 FS	*116.92 FS
41	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
42	1		*TAILLIGHT ASSYR	Broken	223.80 FS	*223.80 FS
43	1		*TAILLIGHT ASSYL	Broken	240.82 FS	*240.82 FS
44	1		*LIGHT ASSYR.LID	Broken	104.70 FS	*104.70 FS
45	1		*LIGHT ASSYL.LID	Broken	104.70 FS	*104.70 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*CAMERA ASSY.RR VI	Not Necessary	270.15 FS	*- FS
47	1		*SENSOR ASSY ,PARKING (4 PCS)	Shorted (2 PCS ONLY)	466.20 FS	*233.10 FS
48	1		*SUB CORDRR BUMPER CORNER SENS	Torn	24.07 FS	*24.07 FS
49	1		*ANTENNA ASSYL.F	Cracked	47.40 FS	*47.40 FS
50	1		*BUZZER ASSYSMART	Not Necessary	49.05 FS	*- FS
51	1		*OIL SHEET	Necessary	32.55 FS	*32.55 FS
52	1		*NUMBER PLATE WITH CASING -L	Serviceable	45.00 FS	*- FS
53	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
54	1		*BODY JOINT SEALANT	Necessary	400.00 FS	*300.00 FS
55	1		*OUTLET ASSY.RR AIR	Broken	6.90 FS	*6.90 FS
56	1		*RUBBER CWINDSHIELD DAM	Necessary	14.77 FS	*14.77 FS
57	1		*RUBBERRR QTR W/SHIELD (3 PCS)	Necessary	23.17 FS	*23.17 FS
58	1		*FASTENER BW/SHIELD (2 PCS)	Necessary	7.95 FS	*7.95 FS
59	1		*FASTENER AW/SHIELD (2 PCS)	Necessary	5.70 FS	*5.70 FS
60	1		*SUPPORT COMPR ,RR.SHELF	Bent	41.77 FS	*41.77 FS
61	1		*SUPPORT COMPL,RR.SHELF	Bent	41.77 FS	*41.77 FS
62	1		*STIFFNER BR.RR.FLOOR SIDE	Bent	23.32 FS	*23.32 FS
63	1		*FRAMER.RR.FRAME RR.UPPER	Bent	35.02 FS	*35.02 FS
64	1		*GUSSETR .RR. PANEL	Necessary	17.70 FS	*17.70 FS
65	1		*SHELF COMPRR PARCEL	Bent	209.32 FS	*209.32 FS
66	1		*LINING ASSY ,R.TRUNK	Distorted	43.42 FS	*43.42 FS
67	1		*LINING ASSY ,L.TRUNK SIDE	Distorted	41.62 FS	*41.62 FS
68	1		*SOLAR FILM ON REAR QTR GLASS	Necessary	150.00 FS	*150.00 FS
69	1		*SOLAR FILM ON REAR QTR GLASS	Necessary	150.00 FS	*150.00 FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	6,634.99 5,785.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	BODY UNDERSIDE COATING	New	400.00	300.00
2	APPLY BODY UNDERSIDE COATING	New	250.00	250.00
3	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	180.00	150.00
4	REMOVE & INSTALL REVERSE SENSORS	New	200.00	160.00
5	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	450.00	350.00
6	RESET VEHICLE SMART ENTRY SYSTEM	New	450.00	350.00
7	REMOVE & INSTALL RR .R QTR GLASS	New	420.00	300.00
8	REMOVE & INSTALL RR .L QTR GLASS	New	420.00	300.00
9	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	New	450.00	350.00
10	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	450.00	325.00
11	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	New	450.00	325.00
12	REMOVE & INSTALL FUEL TANK FUEL PIPES	New	350.00	320.00
13	REMOVE & INSTALL EXHAUST SYSTEM	New	350.00	280.00
14	REMOVE & RENEW RR FLOOR INSULATOR	New	450.00	0.00
15	CUT OFF & RNEEW RR FLOOR PANEL ALIGN CHASSIS FR	New	9,000.00	7,150.00
16	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	4,000.00	3,700.00
17	CUT & RENEW PARCEL SHELF INCLUDING	New	1,950.00	975.00
18	REMOVE & INSTALL RR WINDSCREEN	New	650.00	450.00
19	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	520.00	0.00
Gross Labour Cost (\$\$)			21,390.00	16,035.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >