

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGU 9128M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR DOOR RHS	TO REPAIR SEE LABOUR	940.70	-
1	FRONT DOOR RHS	TO REPAIR SEE LABOUR	1,097.50	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	495.70	-
1	HEADLAMP RHS	SERVICEABLE	492.80	-
1	FRONT BUMPER RETAINER	SERVICEABLE	64.60	-
1	FRONT FENDER	TO REPAIR SEE LABOUR	637.70	-
	LESS 25% DISCOUNT		-932.25	-
			2,796.75	-
	SPECIAL NETT ITEMS			
1	BUMPER CLIPS (SN)	NOT NECESSARY	50.00	-
1	FRONT RIM RHS (SN)	NECESSARY	350.00	250.00
1	FRONT TYRE RHS (SN)	SERVICEABLE	250.00	-
1	REAR RIM RHS (SN)	SERVICEABLE	350.00	-
1	REAR TYRES RHS (SN)	SERVICEABLE	250.00	-
			1,250.00	250.00
	<u>LABOUR</u>			
	PANEL BEAT - ACCIDENT AREA.INCLUSIVE OF THE REPAIR OF REAR DOOR RHS,FRONT DOOR RHS,FRONT BUMPER AND FRONT FENDER.		1,000.00	300.00
	SPRAY PAINT - SIDE SKIRT RHS, FRONT FENDER RHS, DOOR RRHS,DOOR RRHS, FRONT BUMPER.		1,200.00	1,000.00
	RUST PROOFING.	NOT NECESSARY	60.00	-
	REMOVE AND REFIT DOOR COMPONENTS.	NOT NECESSARY	150.00	-
	REMOVE AND REFIT DOOR REGULATOR MOTOR.	NOT NECESSARY	150.00	-
	REMOVE AND REFIT DOOR GLASS TO TRANSFER.	NOT NECESSARY	150.00	-
	CHECK WIRING AND CHECK ALIGNMENT.		60.00	60.00
			2,770.00	1,360.00
	GRAND TOTAL		6,816.75	1,610.00

Report Ref No. CS/AGI22002888/Kvy3n2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		700.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI22002888/Kvy3n2

KONG SENG CHEONG

Licensed Appraiser