



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22002892/Ety3n2 Date: 06/06/2022 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHF 194Y	Veh. Inspected	GBE 4641Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/03/22/2057	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	29/03/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA DYNA 150	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JTFAT35Y80K205508	Colour	SILVER	
Odometer	159598 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	DUNLOP	4 mm	
L/H Front Tyre	195 R15C	DUNLOP	4 mm	
R/H Rear Tyre	195 R15C	DUNLOP	4 mm	
L/H Rear Tyre	195 R15C	DUNLOP	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	24/03/2022	Inspection Date	30/03/2022	
Survey held at	SKYLINK ENGINEERING PTE LTD 48 TOH GUAN ROAD EAST, #01-118, ENTERPRISE HUB, SINGAPORE 608586			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	