



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGC 3399G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	DEFORMED	803.00	803.00
1	FRT BUMPER LH RETAINER	NOT NECESSARY	26.00	-
1	FTR BUMPER TOP CHROME	CUT	186.00	186.00
1	FRT BUMPER LOWER CHROME	CUT	181.00	181.00
1	FRT BUMPER CENTRE GRILLE	NOT NECESSARY	264.00	-
1	FRT GRILLE	CUT	697.00	697.00
1	LH HEADLAMP	CRACKED	2,087.00	2,087.00
1	FRT BUMPER LH FOG LAMP COVER	NOT NECESSARY	64.00	-
	LESS 10% DISCOUNT		-430.80	-395.40
			3,877.20	3,558.60
	<u>LABOUR</u>			
	PANEL BEATING.		600.00	300.00
	SPRAY PAINTING.		600.00	200.00
	WIRING.		30.00	30.00
			1,230.00	530.00
GRAND TOTAL			5,107.20	4,088.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,200.00

Report Ref No. CS/SMO22002894/Avy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.