

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22002908/UQY3E2

**Date:** 13/04/2022

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00087002101		
Claimant Vehicle No :	SLB2446G	Insured Vehicle No :	SLS7538C		
Date of Loss:	26/03/2022	Nature of Claim:	TP	Claim No:	SNM22D202113/C02/TANCHC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB2446G	Engine No:	QR25370520L
Make & Model:	NISSAN TEANA 2.5L CVT, 2.5 (A)	Chassis No:	MNTBCAL33Z0003419
Reg. Date:	31/03/2016 (Man. Year: 2015)	Odometer:	94565 km
Colour:	Black		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,254.50	4,563.25	5,691.25	55.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	1,120.00	1,250.00	52.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,624.50</b>	<b>5,683.25</b>	<b>6,941.25</b>	<b>54.98</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,500.00</b>		
<b>(S\$)</b>	12,624.50	4,500.00	8,124.50	64.36
<b>+ GST 7.00/7.00% (S\$)</b>	883.72	315.00	568.72	64.36
<b>Nett Amount (S\$)</b>	<b>13,508.22</b>	<b>4,815.00</b>	<b>8,693.22</b>	<b>64.36</b>

### INSPECTION

Date of Assignment:	29/03/2022		
Date Inspected:	30/03/2022	Inspected At:	Falcon-Air Auto Services Pte Ltd Blk 9006 Tampines St 93 #01-200 Singapore 528840
Estimated Period of Repair:	4.0 days		

**Adjuster:** MARCUS CHUA

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Apr 2022)
Parts:	143	NISSAN TEANA 2.5L CVT 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB2446G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deep Cut	866.10 FN	*866.10 FN
2	1		*FRONT BUMPER SIDE RETAINER	O/S Bent	64.20 FN	*26.00 FN
3	1		*O/S FOG LAMP GARNISH	Not Necessary	113.70 FN	*- FN
4	1		*O/S FOG LAMP	Not Necessary	166.00 FN	*- FN
5	1		*O/S DAY LIGHT	Cracked	366.00 FN	*345.00 FN
6	1		*O/S HEADLAMP	Cracked	1,610.00 FN	*1,610.00 FN
7	1		*O/S FRONT FENDER	Warped / Bent	770.00 FN	*701.90 FN
8	1		*O/S FRONT FENDER INNER SHIELD	Torn	131.70 FN	*131.70 FN
9	1		*O/S FRONT RIM	Cut	1,319.40 FS	*600.00 FS
10	1		*O/S FRONT WHEEL BEARING	Not Necessary	383.60 FN	*- FN
11	1		*O/S FRONT KNUCKLE ARM	Not Necessary	608.00 FN	*- FN
12	1		*O/S FRONT LOWER ARM	Not Necessary	349.20 FN	*- FN
13	1		*O/S FRONT SHOCK ABSORBER	Not Necessary	384.10 FN	*- FN
14	1		*O/S DRIVE SHAFT	Not Necessary	1,003.90 FN	*- FN
15	1		*STEERING RACK ASSY	Not Necessary	1,842.90 FN	*- FN
16	1		*O/S WING MIRROR ASSY	Damaged	879.60 FN	*611.80 FN
17	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
18	1		*SET O/S FRONT FENDER INNER SHIELD CLIP	Necessary	50.00 FS	*50.00 FS
19	1		*O/S FRONT TYRE	Serviceable	250.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	11,208.40	4,992.50
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	953.90	429.25
Total Parts (\$\$)	10,254.50	4,563.25

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK LIGHT AND WIRING	New	50.00	20.00
2	COMPUTERIZED WHEEL ALIGNMENT	New	120.00	60.00
3	REPLACE FRONT UNDERCARRIAGE	New	200.00	0.00
4	TO DIAGNOSE AND REPROGRAM	New	200.00	60.00
5	LABOUR / PANEL BEATING	New	800.00	400.00
6	SPRAY PAINTING	New	1,000.00	580.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,370.00</b>	<b>1,120.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >