

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002914/KVY3N2**Date:** 29/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00147482101

Claimant Vehicle No : SLW3239X **Insured Vehicle No :** SJS1375T

Date of Loss: 10/02/2022 Nature of Claim: TP Claim No: SNM22D202139/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW3239X**

Make & Model: PEUGEOT 3008 ACTIVE PURETECH, 1.2 EAT6 (A) Engine No: 10XTA40843660

Reg. Date: 07/02/2018 (Man. Year: 2017) Chassis No: VF3MRHNYWHS325029

Colour: Metallic Green Odometer: 48210 km

Engine Capacity: 1199 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65R15 Rear Tyre Size: 215/65R15

Front Left Side: KAPSEN 9 mm Rear Left Side: KAPSEN 9 mm

Front Right Side: KAPSEN 9 mm Rear Right Side: KAPSEN 9 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 10,254.85 | 5,531.85 | 4,723.00 | 46.06 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,520.00 | 1,300.00 | 1,220.00 | 48.41 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 12,774.85 | 6,831.85 | 5,943.00 | 46.52 |
| Approved Total (Overridden) (\$\$) | | 5,450.00 | | |
| Nett Amount (\$\$) | 12,774.85 | 5,450.00 | 7,324.85 | 57.34 |

INSPECTION

Date of Assignment: 29/03/2022

Date Inspected: 30/03/2022 Inspected At: Optima Werkz Pte Ltd (HQ)
10 Ang Mo Kio Industrial Park 2A, #01-05 AMK
Autopoint
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Apr 2022)

Parts: M1-SUV PEUGEOT 3008 ACTIVE PURETECH 1.2 EAT6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLW3239X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|-------------|-------------|--------------|
| 1 | 1 | | *FRONT DOOR LH | Bent | 2,258.48 FL | *1,850.00 FL |
| 2 | 1 | | *FRONT DOOR LOWER GARNISH COVER LH | Bent | 333.25 FL | *333.25 FL |
| 3 | 1 | | *FRONT DOOR WEATHERSTRIP LH | Serviceable | 151.77 FL | *- FL |
| 4 | 1 | | *FRONT DOOR OUTER MOULDING LH | Serviceable | 205.20 FL | *- FL |
| 5 | 1 | | *REAR DOOR LOWER GARNISH COVER LH | Dented | 333.25 FL | *333.25 FL |
| 6 | 1 | | *REAR DOOR LH | Bent | 2,258.48 FL | *1,850.00 FL |
| 7 | 1 | | *REAR DOOR WEATHERSTRIP LH | Serviceable | 151.77 FL | *- FL |
| 8 | 1 | | *REAR DOOR OUTER MOULDING LH | Serviceable | 205.20 FL | *- FL |
| 9 | 1 | | *REAR DOOR UPPER HINGE LH | Repair | 126.50 FL | *- FL |
| 10 | 1 | | *REAR DOOR LOWER HINGE LH | Repair | 126.50 FL | *- FL |
| 11 | 1 | | *REAR DOOR CHECKER LH | Serviceable | 138.60 FL | *- FL |
| 12 | 1 | | *REAR DOOR WINDOW MOTOR WITH REGULATOR LH | Serviceable | 689.60 FL | *- FL |
| 13 | 1 | | *REAR DOOR INNER TRIM BOARD LH | Mtg Cracked | 2,164.78 FL | *1,580.00 FL |
| 14 | 1 | | *ROCKER PANEL LH | Repair | 2,050.90 FL | *- FL |
| 15 | 1 | | *B-PILLAR LH (NPA) | Repair | 0.00 FL | *- FL |
| 16 | 1 | | *FRONT DOOR INNER TRIM BOARD CLIPS LH | Necessary | 50.00 FS | *50.00 FS |
| 17 | 1 | | *REAR DOOR INNER TRIM BOARD CLIPS RH | Necessary | 50.00 FS | *50.00 FS |
| 18 | 1 | | *FRONT DOOR LOWER GARNISH COVER CLIPS LH | Necessary | 40.00 FS | *40.00 FS |
| 19 | 1 | | *REAR DOOR LOWER GARNISH COVER CLIPS LH | Necessary | 40.00 FS | *40.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|------------------|-----------------|
| Sub Total (\$\$) | 11,374.28 | 6,126.50 |
| - List Item Discount on L Items 10.00/10.00% (\$\$) | 1,119.43 | 594.65 |
| Total Parts (\$\$) | 10,254.85 | 5,531.85 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|------------------------|--|----------|------------|----------|
| Labour Items | | | | |
| 1 | LABOUR CHARGES TO REMOVE,REPLACE,REFIX,REPAIR & READJUST ACCIDENT AREAS & ETC | New | 1,000.00 | 500.00 |
| 2 | LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR LH,REAR DOOR LH,ROCKER PANEL LH,B-PILLAR LH & ETC | New | 1,000.00 | 600.00 |
| 3 | LABOUR CHARGES TO REMOVE & REINSTALLED FRONT & REAR DOOR INNER MECHANISM.BACK TO ORIGINAL OPERATIONS | New | 250.00 | 120.00 |
| 4 | TO CHECK WIRING & CENTRAL LOCKING SYSTEM | New | 120.00 | 20.00 |
| 5 | TO TUFF KOTE & UNDERSEAL MATERIALS | New | 150.00 | 60.00 |
| Gross Labour Cost (\$) | | | 2,520.00 | 1,300.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >