

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 7977A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CRACKED	493.00	493.00
1	REAR BUMPER SIDE RETAINER LH	NOT NECESSARY	25.00	-
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	849.00	-
1	REAR FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR DOOR LH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-273.40	-98.60
			1,093.60	394.40
	SPECIAL NETT ITEMS			
1	REAR BUMPER CLIPS (SN)	NECESSARY	25.00	25.00
			25.00	25.00
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR FRONT DOOR LH, REAR FENDER AND REAR DOOR LH.		800.00	300.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		1,000.00	800.00
	TO REMOVE AND REPAIR / REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION.	NOT NECESSARY	90.00	-
	TO REMOVE AND REFIT / REPLACE FRONT DOOR LH FITTING, TRIMMINGS, GARNISH, WINDOW GLASS AND LOCK MECHANISM.	NOT NECESSARY	120.00	-
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	60.00	-
			2,070.00	1,100.00
	GRAND TOTAL		3,188.60	1,519.40

Report Ref No. CS/INC22002917/Rqy3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,200.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. CS/INC22002917/Rqy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser