

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD INV No. AC2302491

3 ANSON ROAD #16-00 INV Date 19/04/2023 SPRINGLEAF TOWER Reference CC3/CT122

SPRINGLEAF TOWER

SINGAPORE 079909

Reference CC3/CTI22002923/Tya3q2

Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHA 4494G

Insured Veh. SJN 6731S

Claim No. SNM22D202084

Policy No. DMHCSNW00001742200

Accident Date 25/03/2022

Inspection Date 28/03/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN	SURANCE (S) PTE LTD		Ref:	CC3/CTI22002923/Tya3q2		
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909		Date:	19/04/2023		
				Code:	CTI		
1.		Policy Particulars	:- THIRD PART	CLAIN	1		
	Insured Veh.	SJN 6731S	Veh. Inspected	k	SHA 4494G		
	Policy No.	DMHCSNW00001742200	Coverage (\$)		0.00		
	Claim No.	SNM22D202084	Excess (\$)		0.00		
	Assign From		Assign Date		28/03/2022		
2.		Vehicle Partic	culars & Condit	ion			
	Make & Model	HYUNDAI 140	c.c		1685		
	Engine No.	HIDDEN	Year of Reg.		2017		
	Chassis No.	KMHLB41UMHU098225	Colour		BLUE		
	Odometer	494032 KM	Steering		IN ORDER		
	Brakes	IN ORDER	Modification		NIL		
	General	GOOD					
3.		Conditi	ons of Tyres				
		Size	Make		Balance		
	R/H Front Tyre	205/60 R16	WEST LAKE		6 mm		
	L/H Front Tyre	205/60 R16	WEST LAKE		6 mm		
	R/H Rear Tyre	205/60 R16	WEST LAKE		6 mm		
	L/H Rear Tyre	205/60 R16	WEST LAKE		6 mm		
4.		Description	on of Damages				
	THE VEHICLE SU	STAINED DAMAGES AT THE RE	AR PORTION.				
	DAMAGES SEE DETAILS.						
5.		Genera	I Information				
	Accident Date	25/03/2022	Inspection Dat	e	28/03/2022		
	Survey held at	COMFORTDELGRO ENGINEER	RING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969					
5a.		Re	emarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b.	Estimate Days of Repair						
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:		2 Work	ing Days		
			<u> </u>				



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4494G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER COVER	DEFORMED	553.00	553.00
1	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER SIDE BRACKET RH	NOT NECESSARY	35.60	-
1	REAR BUMPER REFLECTOR LAMP RH	NOT NECESSARY	32.00	-
1	REAR BUMPER LOWER COVER	NOT NECESSARY	228.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	428.40	-
1	RR BUMPER REINFORCEMENT BRACKET RH	NOT NECESSARY	160.60	-
1	REAR BUMPER SPONGE	NOT NECESSARY	119.50	-
1	EXHAUST SILENCER RH	NOT NECESSARY	967.70	-
1	EXHAUST PIPE CENTRE	NOT NECESSARY	730.10	-
1	EXHAUST PIPE HANGER	NOT NECESSARY	117.10	-
	LESS 20% DISCOUNT		-678.80	-115.00
			2,715.20	460.00
	SPECIAL NETT ITEMS			
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	CUT	50.00	50.00
1	REAR FENDER ADVERTISEMENT LOGO LH (SN)	NECESSARY	100.00	100.00
1	REAR FENDER ADVERTISEMENT LOGO RH (SN)	NECESSARY	100.00	100.00
1	REAR BUMPER REVERSE SENSOR (SN)	NOT WORKING	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			435.70	435.70
	<u>LABOUR</u>			
	PANEL BEATING.		700.00	280.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE/REFIX EXHAUST PIPE .	NOT NECESSARY	150.00	-
	REMOVE/REFIX REVERSE SENSOR .		60.00	30.00
			1,210.00	560.00
	GRAND TOTAL		4,360.90	1,455.70

Report Ref No. CC3/CTI22002923/Tya3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,150.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CC3/CTI22002923/Tya3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

HO LEONG CHUAN

Automotive Assessor

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 4494G

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 4494G

RE-INSPECTION





