

1012

VEHICLE NO	SHC1183M
MAKE	REG 01.03.2019
MODEL	IONIQ G3

CHIANG/CHINA

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		de \$459.40
2	REAR BUMPER SIDE BRACKET LH/RH		u X LH RH? \$55.80
1	REAR BUMPER REINFORCEMENT		u X \$394.80
1	REAR BUMPER CENTRE MOULDING		de \$451.25
2	REAR BUMPER SIDE UNDER RH		u X \$108.00
1	REAR BUMPR REFLECTOR RH		u X \$40.50
2	NUMBER PLATE LAMP LH/RH		\$85.30 u X \$85.30
10	REAR BUMPER CLIPS		\$2.20 net \$22.00
	SUB TOTAL		\$1,617.05
	20.00%		\$323.41
	DISCOUNTED TOTAL		\$1,293.64
2	REAR FENDER ADVERTISEMRNT LH/RH		net \$200.00
2	REAR NUMBER PLATE W/HOLDER		Xan \$55.00
1	REAR REVERSE SENSOR		u \$180.00
			\$435.00
	Labour Charge		
	Panel Beating		
	Spray Painting Charge		350 \$550.00
	Check Lighting and Wiring		250 \$300.00
	Tuff Kote		u X \$60.00
	Remove/refix Reverse sensor		u X \$60.00
	TOTAL LABOUR		30 \$60.00
			\$1,030.00
	ESTIMATE TOTAL		\$2,758.64
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Tamfrin 97495740
inp' 28/3/21 @ 425
c/s rising after report
2 days
tamfrin cl@hants.wm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by _____

Acknowledged by Repairer
Signature: _____
Date: _____