

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002929/AQY3N2**Date:** 27/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00166902103	
Claimant Vehicle No :	SMW1635L	Insured Vehicle No :	SKA3G	
Date of Loss:	28/03/2022	Nature of Claim:	TP	Claim No: SNM22D202144/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW1635L		Engine No:	G4FGKU094690
Make & Model:	HYUNDAI AVANTE, 1.6 (A)		Chassis No:	KMHD841CMKU865794
Reg. Date:	12/04/2019 (Man. Year: 2019)		Odometer:	76319 km
Colour:	Red			
Engine Capacity:	1591 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,933.20	9,351.12	12,582.08	57.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,360.00	2,400.00	6,960.00	74.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	31,293.20	11,751.12	19,542.08	62.45
Approved Total (Overridden) (\$\$)		9,400.00		
Nett Amount (\$\$)	31,293.20	9,400.00	21,893.20	69.96

INSPECTION

Date of Assignment:	30/03/2022	
Date Inspected:	29/03/2022	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	9.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 May 2022)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW1635L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	474.40 FL	*474.40 FL
2	1	*FRONT BUMPER TOWING COVER	Not Necessary	10.00 FL	*- FL
3	1	*FRONT BUMPER NUMBER PLATE HOLDER	Cracked	20.00 FL	*20.00 FL
4	1	*FRONT BUMPER LOWER LIP	Not Necessary	71.70 FL	*- FL
5	2	*FRONT BUMPER CENTER BRACKET	Not Necessary	98.40 FL	*- FL
6	2	*FRONT BUMPER FOGLAMP C/W BRACKET RH	Not Necessary	330.00 FL	*- FL
7	2	*FRONT BUMPER FOG LAMP LOWER GARNISH	Not Necessary	230.80 FL	*- FL
8	2	*FRONT BUMPER SIDE RETAINER	Necessary	32.00 FL	*32.00 FL
9	2	*FRONT BUMPER SIDE AIR VENT	Not Necessary	48.80 FL	*- FL
10	1	*FRONT BUMPER REINFORCEMENT	Dented	695.80 FL	*695.80 FL
11	1	*FRONT BUMPER SPONGE	Cracked	110.70 FL	*110.70 FL
12	1	*FRONT BUMPER LOWER BEAM	Cracked	119.00 FL	*119.00 FL
13	1	*FRONT BUMPER TOP RUBBER	Not Necessary	25.40 FL	*- FL
14	1	*FRONT ENGINE UNDER COVER	Not Necessary	133.30 FL	*- FL
15	2	*FRONT FENDER INNER COWLING	Not Necessary	171.40 FL	*- FL
16	2	*HEAD LAMP	Cracked	6,069.80 FL	*4,792.00 FL
17	2	*HEAD LAMP BOTTOM BRACKET	Not Necessary	194.40 FL	*- FL
18	2	*HEAD LAMP LOWER BRACKET	Not Necessary	48.00 FL	*- FL
19	2	*HEAD LAMP TOP RUBBER	Not Necessary	78.40 FL	*- FL
20	1	*CENTER GRILLE	Cracked	1,214.30 FL	*1,214.30 FL
21	1	*CENTER GRILLE TOP COVER GARNISH	Not Necessary	84.50 FL	*- FL
22	1	*CENTER GRILLE LOGO	Necessary	26.20 FL	*26.20 FL
23	1	*FRONT SUPPORT PANEL	Not Necessary	949.30 FL	*- FL
24	1	*HORN	Not Necessary	78.30 FL	*- FL
25	1	*REAR BUMPER	Torn	459.40 FL	*459.40 FL
26	1	*REAR BUMPER LAMP	N/s Cracked	403.00 FL	*201.50 FL
27	1	*REAR BUMPER LAMP WIRE HARNESS	Not Necessary	121.00 FL	*- FL
28	2	*REAR BUMPER NUMBER PLATE LAMP	Not Necessary	56.00 FL	*- FL
29	1	*REAR BUMPER CENTRE (BLACK)	Deformed	353.50 FL	*353.50 FL
30	2	*REAR BUMPER RETAINER	Necessary	58.80 FL	*58.80 FL
31	1	*REAR BUMPER REINFORCEMENT	Cracked	294.80 FL	*294.80 FL
32	2	*REAR BUMPER REINFORCEMENT BRACKET	Damaged	10.00 FL	*10.00 FL
33	1	*REAR BUMPER BRACKET 5 PCS	Damaged (3pcs only)	393.00 FL	*60.00 FL
34	1	*REAR BUMPER SIDE INNER LOWER GARNISH	Not Necessary	37.20 FL	*- FL
35	2	*REAR FENDER INNER COWLING (REAR)	Not Necessary	120.00 FL	*- FL
36	2	*REAR FENDER INNER TRIM	Not Necessary	416.00 FL	*- FL
37	1	*TAILLAMP	N/s Cracked	2,104.20 FL	*1,052.10 FL
38	2	*TAILLAMP PANEL	Not Necessary	386.20 FL	*- FL
39	1	*BOOTLID	Repair	2,049.80 FL	*- FL
40	2	*BOOTLID LAMP	Not Necessary	1,328.40 FL	*- FL
41	1	*BOOTLID LOGO	Necessary	54.70 FL	*54.70 FL
42	1	*BOOTLID EMBLEM AVANTE	Necessary	31.20 FL	*31.20 FL
43	1	*BOOTLID OUTER SWITCH BUTTON	Not Necessary	196.20 FL	*- FL
44	1	*BOOTLID DETECTOR (OUTER)	Cracked	369.70 FL	*165.00 FL
45	1	*BOOTLID DETECTOR (INNER)	Not Necessary	358.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*BOOTLID DETECTOR WIRE HARNESS	Not Necessary	426.70 FL	*- FL
47	1		*BOOTLID REVERSE CAMERA	Not Necessary	826.10 FL	*- FL
48	2		*BOOTLID HINGE	Not Necessary	188.60 FL	*- FL
49	2		*BOOTLID STOPPER	Not Necessary	14.00 FL	*- FL
50	1		*BOOTLID INSULATOR	Not Necessary	146.80 FL	*- FL
51	1		*BOOTLID TOP LOCK	Not Necessary	116.20 FL	*- FL
52	1		*BOOTLID LOWER LOCK	Not Necessary	16.00 FL	*- FL
53	1		*BOOTLID WEATHER STRIP	Cut	92.50 FL	*92.50 FL
54	1		*REAR END PANEL	Dented	454.60 FL	*454.60 FL
55	1		*REAR END PANEL TOP GARNISH	Cracked	59.80 FL	*59.80 FL
56	1		*REAR FLOOR PANEL TOP BOARD	Deformed	219.10 FL	*219.10 FL
57	1		*REAR TOOLS SPONGE	Not Necessary	164.90 FL	*- FL
58	1		*REAR BLIND SPOT SENSOR	Not Necessary	1,249.60 FL	*- FL
59	1		*FRONT NUMBER PLATE	Cracked	80.00 FS	*60.00 FS
60	1		*FRONT BUMPER CLIP (SET)	Necessary	80.00 FS	*30.00 FS
61	1		*FRONT ENGINE UNDER COVER CLIP (SET)	Not Necessary	80.00 FS	*- FS
62	1		*CENTER GRILLE CLIP (SET)	Necessary	60.00 FS	*30.00 FS
63	1		*FRONT FENDER INNER COWLING CLIP (SET)	Not Necessary	80.00 FS	*- FS
64	1		*FRONT AIRCON CONDENSER SIDE GARNISH CLIP (SET)	Not Necessary	40.00 FS	*- FS
65	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS
66	1		*REAR NUMBER PLATE	Cut	80.00 FS	*60.00 FS
67	1		*REAR BUMPER CLIP (SET)	Necessary	80.00 FS	*30.00 FS
68	1		*REAR BUMPER SIDE INNER LOWER GARNISH CLIP (SET)	Not Necessary	80.00 FS	*- FS
69	1		*BOOT LID INSULATOR CLIP (SET)	Not Necessary	80.00 FS	*- FS
70	1		*TAIL LAMP CLIP (SET)	Necessary	60.00 FS	*20.00 FS
71	2		*TAILLAMP PANEL SEALANT	Not Necessary	240.00 FS	*- FS
72	1		*REAR FENDER INNER COWLING CLIP (SET)	Not Necessary	80.00 FS	*- FS
73	1		*REAR FENDER INNER TRIM CLIPS (SET)	Not Necessary	80.00 FS	*- FS
74	1		*REAR END PANEL TOP GARNISH CLIP (SET)	Necessary	40.00 FS	*20.00 FS
75	1		*REAR END PANEL INSULATION SEALANT	Necessary	150.00 FS	*60.00 FS
76	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	350.00 FS	*- FS
77	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,911.50	11,561.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,978.30	2,210.28
Total Parts (\$\$)	21,933.20	9,351.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	1,400.00	400.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	250.00
3	REMOVE AND REFIX AIRCON CONDENSER AND REFILL AIRCON GAS	New	120.00	0.00
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	0.00
5	REFOCUS HEADLAMP BEAM	New	60.00	0.00
6	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	2,400.00	700.00
7	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	800.00
8	TUFF COAT	New	250.00	60.00
9	WIRING CHECK	New	180.00	30.00
10	REMOVE AND REFIX UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	350.00	60.00
11	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
12	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
13	REAR CHASSIS ALIGNMENT	New	250.00	0.00
14	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
15	TRANSFER BOOTLID MECHANISM	New	80.00	0.00
16	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	New	80.00	0.00
17	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
18	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	New	250.00	0.00
Gross Labour Cost (\$\$)			9,360.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >