



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 9192S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER (CONSISTENT)	BUCKLED	875.60	855.10
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	483.20	382.00
1	REAR LOWER BUMPER (CONSISTENT)	DENTED / CUT	550.60	465.10
2	REAR BUMPER SIDE RETAINER @\$75.10 (CONSISTENT)	SERVICEABLE	150.20	-
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	725.70	-
	LESS 25% DISCOUNT		-696.33	-425.55
			2,088.97	1,276.65
	<b><u>SPECIAL NETT ITEMS</u></b>			
15	REAR BUMPER CLIP @\$2.00 (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	REAR REVERSE SENSOR (SN) (CONSISTENT)	DENTED	200.00	200.00
			230.00	230.00
	<b><u>LABOUR</u></b>			
	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		600.00	200.00
	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION.		500.00	200.00
	CHECK AND RECONNECT WIRING.		40.00	15.00
			1,140.00	415.00
	<b>GRAND TOTAL</b>		<b>3,458.97</b>	<b>1,921.65</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,500.00</b>

Report Ref No. CS/ASM22002930/Kty3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.