



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 3195H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (CONSISTENT)	BUCKLED	670.00	670.00
2	REAR BUMPER SIDE RETAINER @\$45.00 (CONSISTENT)	N/S DISTORTED	90.00	45.00
1	REAR BUMPER BEAM (CONSISTENT)	TO REPAIR SEE LABOUR	280.00	-
	LESS 10% DISCOUNT		-104.00	-
	LESS 20% DISCOUNT		-	-143.00
			936.00	572.00
1	REAR LOWER LID (CONSISTENT)	BUCKLED	380.00	380.00
1	REAR LOWER LID CHROME (CONSISTENT)	NECESSARY	80.00	80.00
	LESS 20% DISCOUNT		-	-92.00
			460.00	368.00
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR REVERSE SENSORS (SN) (CONSISTENT)	SHORTED	280.00	200.00
			280.00	200.00
<u>LABOUR</u>				
	LABOUR CHARGES TO RENEW ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER BEAM. TO RESPRAY AFFECTED PORTION.		600.00	300.00
			500.00	400.00
			1,100.00	700.00
GRAND TOTAL			2,776.00	1,840.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,450.00

Report Ref No. CS/ASM22002932/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.