



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## OPINION ON REPAIR COST FOR VEHICLE NO. BICYCLE

Qty	Description of Parts	Condition	Recommended (\$)
<b>REPLACEMENT OF PARTS</b>			
1	SET CANYON SPEEDMAX CF FRAME (CONSISTENT) }	BENT	5,391.72
1	CANYON SPEEDMAX CF HANDLEBAR (CONSISTENT) }	BENT	-
1	SET SHIMANO DURA-ACE SHIFTER (TIME TRIAL) (CONSISTENT) (NPA)	DISTORTED	-
1	SET SHIMANO DURA-ACE BRAKE LEVEL (CONSISTENT) (NPA)	JAMMED	-
1	ASSIOMA FAVERO POWER METER (CONSISTENT) (NPA)	NOT WORKING	-
1	SHIMANO PEDALS (CONSISTENT)	BENT	1,006.75
1	HELMET (CONSISTENT)	CRACKED	442.03
			6,840.50
<b>GRAND TOTAL</b>			<b>6,840.50</b>

<b>RECOMMENDED COST OF REPAIRS</b>	<b>6,840.50</b>
------------------------------------	-----------------

Report Ref No. CS/ASM22002937/Gvy3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.