

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002938/UVY3N2**Date:** 25/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00003122201

Claimant Vehicle No : SLZ480T **Insured Vehicle No :** SLV3706U

Date of Loss: 26/03/2022 Nature of Claim: TP Claim No: SNM22D202100/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ480T**

Make & Model: HONDA SHUTTLE, 1.5 (A) Engine No: L15B5461570

Reg. Date: 20/04/2018 (Man. Year: 2017) Chassis No: GK81201323

Colour: White Odometer: 76771 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,603.20	4,394.40	2,208.80	33.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	970.00	160.00	14.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,733.20	5,364.40	2,368.80	30.63
Approved Total (Overridden) (\$\$)		4,250.00		
(\$\$)	7,733.20	4,250.00	3,483.20	45.04
+ GST 7.00/7.00% (\$\$)	541.32	297.50	243.82	45.04
Nett Amount (\$\$)	8,274.52	4,547.50	3,727.02	45.04

INSPECTION

Date of Assignment: 05/04/2022

Date Inspected: 04/04/2022 Inspected At: SME MOTOR PTE LTD
1 KAKI BUKIT AVE 6
#02-15 (AUTOBAY @KAKI BUKIT)
SINGAPORE 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Apr 2022)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ480T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET	Dented	711.00 FL	*711.00 FL
2	1		*FRT BONNET LOCK	Serviceable	128.00 FL	*- FL
3	1		*FRT GRILLE	Cracked	285.00 FL	*285.00 FL
4	1		*GRILLE OUTER MOULDING	Cracked	353.00 FL	*353.00 FL
5	1		*GRILLE CENTRE LOGO	Not Necessary	38.00 FL	*- FL
6	4		*GRILLE CLIPS	Not Necessary	22.00 FL	*- FL
7	1		*GRILLE CHROME	Cracked	195.00 FL	*195.00 FL
8	1		*FRT BUMPER	Dented/Deformed	988.00 FL	*988.00 FL
9	2		*FRT BUMPER RETAINER	Bent	50.00 FL	*50.00 FL
10	10		*FRT BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
11	1		*FRT BUMPER REINFORCEMENT	Dented	328.00 FL	*328.00 FL
12	1		*FRT BUMPER LOWER GARNISH	Not Necessary	158.00 FL	*- FL
13	1		*HEADLAMP	O/s Cracked/N/s Not Necessary	4,474.00 FL	*2,237.00 FL
14	1		*HEADLAMP SUPPORT TOP GARNISH	Not Necessary	79.00 FL	*- FL
15	8		*SUPPORT TOP GARNISH CLIPS	Not Necessary	44.00 FL	*- FL
16	1		*HEADLAMP LOWER BRACKET	O/s Cracked/N/s Not Necessary	110.00 FL	*55.00 FL
17	1		*FRT BONNET LOCK GARNISH	Cracked	186.00 FL	*186.00 FL
18	1		*FRT NUMBER PLATE	Cracked	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,244.00	5,483.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,640.80	1,088.60
Total Parts (\$)	6,603.20	4,394.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	LABOUR CHARGE	New	500.00	400.00
3	SPRAY PAINTING	New	600.00	550.00
Gross Labour Cost (\$)			1,130.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >