

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002941/RVY3M4**Date:** 01/06/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00102052100
Claimant Vehicle No : SMK3368H **Insured Vehicle No :** GBL4667M
 Date of Loss: 26/03/2022 Nature of Claim: TP Claim No: SNM22D202111/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMK3368H**
 Make & Model: KIA CERATO, 1.6 EX (A) Engine No: G4FGJH722094
 Reg. Date: 05/04/2019 (Man. Year: 2018) Chassis No: KNAF3416MK5031166
 Colour: Grey Odometer: 43759 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,091.00	1,358.00	4,733.00	77.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,000.00	5,750.00	2,250.00	28.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,091.00	7,108.00	6,983.00	49.56
+ GST 7.00/7.00% (S\$)	986.37	497.56	488.81	49.56
Nett Amount (S\$)	15,077.37	7,605.56	7,471.81	49.56

INSPECTION

Date of Assignment: 29/03/2022
 Date Inspected: 18/04/2022 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
 209 Pandan Gardens
 Singapore 609339
 Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Jun 2022)
Parts: 143	KIA CERATO 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMK3368H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-FR BUMPER	Cracked	633.00 FS	*633.00 FS
2	1		*GRILLE-FRONT BUMPER	Not Necessary	262.00 FS	*- FS
3	1		*ABSORBER-FRONT BUMPER ENERGY	Not Necessary	84.00 FS	*- FS
4	1		*AIR DUCT-FR BUMPER, RH	Not Necessary	14.00 FS	*- FS
5	1		*LAMP ASSY-SIDE REPEATER, RH	Not Necessary	164.00 FS	*- FS
6	1		*MOULDING-FRONT BUMPER, RH	Not Necessary	36.00 FS	*- FS
7	1		*BRACKET-FR BUMPER UPR SIDE MTG	Cracked	31.00 FS	*31.00 FS
8	1		*PANEL-FENDER, RH	Bent	430.00 FS	*430.00 FS
9	1		*LAMP ASSY-HEAD, RH	Not Necessary	1,247.00 FS	*- FS
10	1		*GUARD ASSY-FRONT WHEEL, RH	Not Necessary	95.00 FS	*- FS
11	2		*HUB ASSY-FR WHEEL	Not Necessary	872.00 FS	*- FS
12	1		*ARM COMPLETE-FR LWR, RH	Not Necessary	286.00 FS	*- FS
13	1		*ARM COMPLETE-FR LWR, LH	Not Necessary	286.00 FS	*- FS
14	1		*BEAM COMPLETE-FR BUMPER	Not Necessary	686.00 FS	*- FS
15	1		*CARRIER ASSY-FRONT END MODULE	Not Necessary	675.00 FS	*- FS
16	1		*FRT TYRE LH (90%)	Cut	260.00 FS	*234.00 FS
17	1		*SUNDRY	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	6,091.00	1,358.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, FRT FENDER RH	New	1,600.00	1,280.00
2	SPRAY PAINT FOR FRT BUMPER, FRT FENDER RH	New	1,100.00	1,100.00
3	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
4	TRANSFER FRT RIM RH & LH	New	60.00	0.00
5	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	280.00
7	RENEW FRT UNDER CARRIAGE	New	640.00	0.00
8	SUPPLY FRT RIM RH & LH	New	3,000.00	2,400.00
9	SUPPLY FRT BUMPER SKIRT	New	40.00	40.00
10	REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR	New	100.00	0.00
11	TOP UP AIRCON GAS	New	80.00	0.00
12	REDO FRT BUMPER, FRT FENDER RH WRAPPING	New	950.00	500.00
			Gross Labour Cost (\$)	8,000.00
				5,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >