

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22002942/EQY3N2**Date:** 14/04/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00120782101

**Claimant Vehicle  
No :** SNB207U**Insured Vehicle  
No :** SFW5977G

Date of Loss: 25/03/2022

Nature of Claim: TP

Claim  
No: SNM22D202114/C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SNB207U**

Make &amp; Model: TOYOTA PRIUS, 1.5 (A)

Engine No: 2ZR2G92623

Reg. Date: 28/07/2021 (Man. Year: 2020)

Chassis No: JTDKB3FU003091932

Colour: Silver

Odometer: 60520 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

Front Tyre Size: 195/60R15

Rear Tyre Size:

195/60R15

Front Left Side: Dunlop 4 mm

Rear Left Side:

Dunlop 4 mm

Front Right Side: Dunlop 4 mm

Rear Right Side:

Dunlop 4 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>          | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                          | 1,738.80          | 1,005.00          | 733.80            | 42.20         |
| Miscellaneous Items            | 0.00              | 0.00              | 0.00              |               |
| Labour                         | 4,290.00          | 1,670.00          | 2,620.00          | 61.07         |
| Paintwork Labour               | 0.00              | 0.00              | 0.00              |               |
| Towing                         | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (\$\$)</b>      | <b>6,028.80</b>   | <b>2,675.00</b>   | <b>3,353.80</b>   | <b>55.63</b>  |
| <b>+ GST 7.00/7.00% (\$\$)</b> | 422.02            | 187.25            | 234.77            | 55.63         |
| <b>Nett Amount (\$\$)</b>      | <b>6,450.82</b>   | <b>2,862.25</b>   | <b>3,588.57</b>   | <b>55.63</b>  |

**INSPECTION**

Date of Assignment: 30/03/2022

Date Inspected: 30/03/2022

Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)  
2 Pandan Crescent  
Singapore 128462

Estimated Period of Repair: 3.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |  |  |
|----------------------|--|--|
| <b>Part Source:</b>  | MRM-SG   | Version: 1.0 (Last Synchronised: 14 Apr 2022)          |
| <b>Parts:</b>        | 144  | TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                      |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SNB207U)   |  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

### Recommended Parts

| No. | Qty | Part No. | Particulars         | Condition     | Repairer's                | Amount          |
|-----|-----|----------|---------------------|---------------|---------------------------|-----------------|
| 1   | 1   |          | *REINFORCEMENT      | Not Necessary | 353.10 FS                 | *- FS           |
| 2   | 1   |          | *RETAINER,RR BUMPER | Not Necessary | 140.50 FS                 | *- FS           |
| 3   | 1   |          | *COVER,RR BUMPER    | Broken        | 515.10 FS                 | *515.10 FS      |
| 4   | 1   |          | *COVER,RR BUMPER    | Not Necessary | 23.40 FS                  | *- FS           |
| 5   | 10  |          | *PIECE,RR BUMPER    | Necessary     | 43.00 FS                  | *43.00 FS       |
| 6   | 1   |          | *GUARD,RR BUMPER    | Cut           | 396.90 FS                 | *396.90 FS      |
| 7   | 1   |          | *SEAL,RR BUMPER     | Not Necessary | 125.40 FS                 | *- FS           |
| 8   | 1   |          | *REFLECTOR ASSY     | Not Necessary | 41.40 FS                  | *- FS           |
| 9   | 1   |          | *SUNDRIES           | Necessary     | 100.00 FS                 | *50.00 FS       |
|     |     |          |                     |               | <b>Total Parts (\$\$)</b> | <b>1,738.80</b> |
|     |     |          |                     |               |                           | <b>1,005.00</b> |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars  | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--|----------|-----------------|-----------------|
| <b>Labour Items</b>             |  |          |                 |                 |
| 1                               | DRILL HOLE AND INSTALL REVERSE SENSOR                            | New      | 180.00          | 180.00          |
| 2                               | RESET ECU UPON COMPLETION OF REPAIR                              | New      | 180.00          | 180.00          |
| 3                               | REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA | New      | 2,160.00        | 720.00          |
| 4                               | RESPRAY ACC AFF AREA   | New      | 1,770.00        | 590.00          |
| <b>Gross Labour Cost (\$\$)</b> |  |          | <b>4,290.00</b> | <b>1,670.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >