

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22002946/EVCN2**Date:** 24/06/2022**REFERENCE**

Insured/Claimant:	LIU HUILING	Policy No:	7210084009	
Date of Loss:	26/03/2022	Nature of Claim:	OD	Claim No: 3826062955SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB1570M		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC45197
Reg. Date:	30/07/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF39M1146798
Colour:	Grey	Odometer:	13036 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$185,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65R17	Rear Tyre Size:	215/65R17
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,992.00	3,030.16	13,961.84	82.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,112.00	3,652.00	7,460.00	67.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	28,104.00	6,682.16	21,421.84	76.22
- Excess (\$\$)	800.00	800.00	0.00	0.00
(\$\$)	27,304.00	5,882.16	21,421.84	78.46
+ GST 7.00/7.00% (\$\$)	1,911.28	411.75	1,499.53	78.46
Nett Amount (\$\$)	29,215.28	6,293.91	22,921.37	78.46

INSPECTION

Date of Assignment:	30/03/2022	
Date Inspected:	30/03/2022	Inspected At: 24 BENOI SECTOR SINGAPORE 629857 REPAIRER: PREMIUM AUTOMOBILES PTE LTD
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	1,073.00 FS	*- FS
2	1		*FRONT BUMPER SPOILER	Not Necessary	426.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION-RH	Not Necessary	43.00 FS	*- FS
4	1		*FRONT FENDER-RH	Dented	1,445.00 FS	*1,156.00 FS
5	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	66.00 FS	*- FS
6	1		*FRONT FENDER BRACE-RH	Not Necessary	98.00 FS	*- FS
7	1		*FRONT FENDER BRACKET-RH	Not Necessary	39.00 FS	*- FS
8	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	260.00 FS	*- FS
9	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	105.00 FS	*- FS
10	1		*FRONT FENDER COVER-RH	Not Necessary	18.00 FS	*- FS
11	1		*HEADLIGHT MOUNTING-RH	Not Necessary	132.00 FS	*- FS
12	1		*HEADLIGHT-RH	Not Necessary	5,952.00 FS	*- FS
13	1		*BONNET	Repair	3,695.00 FS	*- FS
14	1		*BONNET IMPACT PROTECTION-CENTER	Not Necessary	31.00 FS	*- FS
15	2		*BONNET HINGE-LH/RH	Not Necessary	162.00 FS	*- FS
16	2		*BONNET WHEEL ARCH COVER-LH/RH	Broken	566.00 FS	*452.00 FS
17	1		*FRONT WINDSCREEN	Broken	1,246.00 FS	*996.80 FS
18	1		*RAIN SENSOR GEL FOIL	Necessary	130.00 FS	*104.00 FS
19	1		*PRIMER	Necessary	22.00 FS	*17.36 FS
20	2		*AERO WIPER ARM-LH/RH	Not Necessary	239.00 FS	*- FS
21	1		*AERODYNAMIC WIPER BLADES	Cut	103.00 FS	*82.40 FS
22	1		*FRONT WINDSCREEN WATER DEFLECTOR STRIP-RH	Not Necessary	52.00 FS	*- FS
23	1		*FRONT DOOR WINDOW SLOT SEAL TRIM STRIP-RH OUTER	Not Necessary	251.00 FS	*- FS
24	1		*FRONT DOOR WINDOW GUIDE TRIM STRIP-RH	Not Necessary	287.00 FS	*- FS
25	1		*FRONT DOOR CORNER TRIM-RH	Not Necessary	51.00 FS	*- FS
26	1		*FRONT WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
27	1		*SUNDRIES	Necessary	300.00 FS	*21.60 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 16,992.00 3,030.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RHS FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAYING OF RHS FRONT DOOR	New	280.00	0.00
4	TO RENEW FRONT WINDSCREEN	New	480.00	480.00
5	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN	New	400.00	0.00
6	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN	New	200.00	150.00
7	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER,BONNET AND RHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	3,200.00	1,250.00
8	TO RESPRAY FRONT BUMPER,BONNET,HINGES,RHS FRONT FENDER,RHS FRONT DOOR AND RHS UPPER A-PILLAR	New	5,000.00	1,100.00
9	TO CARRY OUT CLEAN UP FOR INTERIOR	New	480.00	480.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			11,112.00	3,652.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >