



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNE 5287P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (SN)	SCRATCHED	1,312.82	1,312.82
1	RH/BASIC CARRIER FOR BUMPER (SN)	NOT NECESSARY	84.72	-
1	REAR LOWER BLACK TRIM, BUMPER (SN)	SCRATCHED	460.31	460.31
1	REAR BUMPER TRIM STRIP (SN)	NECESSARY	150.91	150.91
1	RH/REAR LAMP COMBINATION (SN)	NOT NECESSARY	697.17	-
			2,705.93	1,924.04
	<u>LABOUR</u>			
	DISASSEMBLE AND REPLACE ATTACHED PARTS & REFINISH.		1,440.00	960.00
	RESPRAY REAR BUMPER.		960.00	800.00
	USING XENTRY DIAGNOSTIC TO CHECK CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.		380.00	380.00
	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE.		120.00	120.00
			2,900.00	2,260.00
	GRAND TOTAL		5,605.93	4,184.04
RECOMMENDED COST OF REPAIRS				4,184.04

Report Ref No. CS/FCI22002949/Rqy3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.