



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 ATTN: JEFFREY NG		Ref: CS3/AIG21007359/Eqy3e2-1 Date: 11/04/2022 Code: AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMA 603B	Veh. Inspected	FBK 5575T
Policy No.		Coverage (\$)	0.00
Claim No.	1645763836SG	Excess (\$)	0.00
Assign From	JEFFREY NG	Assign Date	30/03/2022
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA XMAX	c.c	292
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	MH3SH0842LK010919	Colour	BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	120/70-15	DUNLOP	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70-14	DUNLOP	4 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/06/2021	Inspection Date	06/07/2021
Survey held at	HUP HIN BLK 1006 BUKIT MERAH LANE 2 #01-02 SINGAPORE 159762		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	