

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22002958/AQY3E2

**Date:** 04/07/2022

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00033612201		
<b>Claimant Vehicle No :</b>	SKR6756M	<b>Insured Vehicle No :</b>	SLS6866L		
Date of Loss:	25/03/2022	Nature of Claim:	TP	Claim No:	SNM22D202070/C02/TANCHC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKR6756M</b>		
Make & Model:	VOLKSWAGEN POLO GP, 1.2 TSI ABS D/AIRBAG 2WD 5DR (A)	Engine No:	CJZ406710
Reg. Date:	27/02/2015 (Man. Year: 2014)	Chassis No:	WVWZZZ6RZFU048467
Colour:	Blue	Odometer:	98452 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,293.46	5,249.05	8,044.41	60.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	1,570.00	2,020.00	56.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,883.46</b>	<b>6,819.05</b>	<b>10,064.41</b>	<b>59.61</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,450.00</b>		
<b>Nett Amount (S\$)</b>	<b>16,883.46</b>	<b>5,450.00</b>	<b>11,433.46</b>	<b>67.72</b>

### INSPECTION

Date of Assignment:	30/03/2022	
Date Inspected:	30/03/2022 Inspected At:	KS AUTOMOBILE (HQ) 60 JALAN LAM HUAT,CARROS CENTRE, #05-68 Singapore 737869
Estimated Period of Repair:	5.0 days	

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 04 Jul 2022)

**Parts:** 144 VOLKSWAGEN POLO GP 1.2 TSI ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SKR6756M)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE ASSY	Repair	1,600.66 F	*- FL
2	1		*TAILGATE INNER LOCK	Not Necessary	242.00 F	*- FL
3	1		*TAILGATE EMBLEM TSL	Necessary	98.00 F	*98.00 FL
4	1		*TAILGATE EMBLEM POLO	Necessary	98.00 F	*98.00 FL
5	1		*TAILGATE EMBLEM BLUEMOTION	Necessary	98.00 F	*98.00 FL
6	1		*TAILGATE WEATHERSTRIP	Cut	249.00 F	*249.00 FL
7	1		*REAR BUMPER	Deformed	1,665.00 F	*1,063.00 FL
8	2		*REAR BUMPER SIDE RETAINER	Not Necessary	240.00 F	*- FL
9	1		*REAR BUMPER REINFORCEMENT	Dented	845.00 F	*455.00 FL
10	1		*REAR BUMPER UNDER COVER	Not Necessary	312.00 F	*- FL
11	2		*REAR BUMPER REFLECTOR	Not Necessary	224.00 F	*- FL
12	2		*REAR NUMBER PLATE LAMP	Not Necessary	170.00 F	*- FL
13	2		*FRONT PASSENGER AND DRIVER SEAT BELT	Activated	1,796.00 F	*1,796.00 FL
14	1		*REAR END PANEL	Dented	658.00 F	*658.00 FL
15	1		*REAR END PANEL TOP GARNISH	Deformed	325.50 F	*325.50 FL
16	2		*REAR FENDER INNER SHIELD	Not Necessary	250.00 F	*- FL
17	2		*REAR FENDER INNER GARNISH	Not Necessary	1,178.80 F	*- FL
18	1		*EXHAUST MUFFLER	Not Necessary	1,445.00 F	*- FL
19	1		*EXHAUST HEAT SHIELD	Not Necessary	287.00 F	*- FL
20	2		*EXHAUST MOUNTING RUBBER	Not Necessary	56.00 F	*- FL
21	8		*REAR BUMPER CLIPS	Necessary	52.00 FS	*30.00 FS
22	9		*REAR FENDER COWLING CLIPS	Not Necessary	58.50 FS	*- FS
23	6		*END PANEL TOP GARNISH CLIPS	Not Necessary	39.00 FS	*- FS
24	1		*REAR NUMBER PLATE	Dented	50.00 FS	*50.00 FS
25	4		*TAILLAMP CLIP	Not Necessary	48.00 FS	*- FS
26	16		*REAR FENDER INNER TRIM CLIPS	Not Necessary	104.00 FS	*- FS
27	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
28	1		*REAR FLOOR INSULATION SEAL	Not Necessary	180.00 FS	*- FS
29	2		*REVERSE SENSOR	Damaged	560.00 FS	*560.00 FS
30	1		*REAR BUMPER CENTRE BRACKET	Cracked	214.00 F	*214.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>13,293.46</b>	<b>5,754.50</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$)</b>	<b>0.00</b>	<b>505.45</b>
<b>Total Parts (\$)</b>	<b>13,293.46</b>	<b>5,249.05</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	New	1,200.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	600.00
3	TUFF COAT	New	250.00	80.00
4	WIRING AND BULB CHECK	New	80.00	30.00
5	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY & ROOF LINING TO FACILIATE REPAIR	New	250.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REMOVE AND REFIX SEAT BELT	New	200.00	150.00
8	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	150.00	0.00
9	REMOVE AND REFIX EXHAUST MUFFLER	New	180.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,590.00</b>	<b>1,570.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >