

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002959/KPA3Q2**Date:** 24/02/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070166275
Claimant Vehicle No :	SNB9906B	Insured Vehicle No :	YL135K
Date of Loss:	28/03/2022	Nature of Claim:	TP
		Claim No:	1861469640SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB9906B	Engine No:	HIDDEN
Make & Model:	TESLA MODEL 3 STANDARD RANGE, (A)	Chassis No:	LRW3F7FJ5MC282819
Reg. Date:	24/09/2021 (Man. Year: 2021)	Odometer:	4517 km
Colour:	Metallic Dark Blue		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35Z R18	Rear Tyre Size:	235/35Z R18
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,422.29	12,119.31	4,302.98	26.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,220.00	4,330.00	2,890.00	40.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,642.29	16,449.31	7,192.98	30.42
+ GST 7.00/7.00% (S\$)	1,654.96	1,151.45	503.51	30.42
Nett Amount (S\$)	25,297.25	17,600.76	7,696.49	30.42
+ Loss of Use (25.0 x S\$100.00/day) (S\$)		2,500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		20,102.76		
Global Sum Settlement (S\$)		20,100.00		

INSPECTION

Date of Assignment:	30/03/2022		
Date Inspected:	30/03/2022	Inspected At:	Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road Singapore 159143
Estimated Period of Repair:	21.0 days		

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	728.97 FL	*728.97 FL
2	1		*REAR BOOTLID TESLA EMBLEM	Necessary	37.38 FL	*37.38 FL
3	1		*REAR BOOTLID LAMP RH	Broken	177.57 FL	*177.57 FL
4	1		*REAR BOOTLID OUTER SWITCH HANDLE	Dented	121.50 FL	*121.50 FL
5	1		*REAR BOOTLID MECHANISM LOCK	Jammed	54.21 FL	*54.21 FL
6	1		*REAR BOOTLID LOCK STRIKER	Repair	52.34 FL	*- FL
7	1		*REAR BOOTLID INNER TRIM BOARD	Mtg Cracked	345.79 FL	*345.79 FL
8	1		*REAR BOOTLID HINGE LH	Distorted	61.68 FL	*61.68 FL
9	1		*REAR BOOTLID HINGE RH	Bent	61.68 FL	*61.68 FL
10	1		*REAR BOOTLID STRUT LH	Punctured	93.46 FL	*93.46 FL
11	1		*REAR BOOTLID STRUT RH	Punctured	93.46 FL	*93.46 FL
12	1		*REAR TAIL LAMP RH	Broken	280.37 FL	*280.37 FL
13	1		*REAR TAIL LAMP BRACKET RH	Necessary	2.80 FL	*2.80 FL
14	1		*REAR TAIL LAMP REFLECTOR RH	Missing	36.45 FL	*36.45 FL
15	1		*REAR BUMPER	Bent / Cracked	663.55 FL	*663.55 FL
16	1		*REAR BUMPER SIDE BRACKET RH	Cracked	7.48 FL	*7.48 FL
17	1		*REAR BUMPER CENTER BRACKET	Bent	52.34 FL	*52.34 FL
18	1		*REAR BUMPER LOWER LIP	Serviceable	140.19 FL	*- FL
19	1		*REAR BUMPER UNDER COVER	Serviceable	205.61 FL	*- FL
20	1		*REAR BUMPER REFLECTOR RH	Cracked	20.56 FL	*20.56 FL
21	3		*REAR BUMPER PARKING SENSOR	Shorted (2 PCS ONLY)	476.64 FL	*317.76 FL
22	1		*REAR BUMPER PARKING SENSOR BRACKET (3 PCS)	Necessary (2 PCS ONLY)	14.01 FL	*9.34 FL
23	1		*REAR BUMPER REINFORCEMENT	Repair	271.03 FL	*- FL
24	1		*REAR END PANEL	Bent	448.60 FL	*448.60 FL
25	1		*REAR END PANEL TOP GARNISH	Mtg Cracked	299.07 FL	*299.07 FL
26	1		*REAR FENDER RH	Bent	1,242.99 FL	*1,242.99 FL
27	1		*REAR FENDER QUARTER GLASS RH	Necessary	280.37 FL	*280.37 FL
28	1		*REAR FENDER INNER SHIELD RH	Deformed	116.82 FL	*116.82 FL
29	1		*REAR FENDER INNER PANEL RH	Repair	962.62 FL	*- FL
30	1		*REAR FENDER INNER PANEL EXTENSION RH	Bent	112.15 FL	*112.15 FL
31	1		*REAR FENDER INNER AIR VENT RH	Dented	14.95 FL	*14.95 FL
32	1		*REAR WINDSCREEN GLASS	Cracked	644.86 FL	*644.86 FL
33	1		*REAR WINDSCREEN TOP MOULDING	Necessary	88.79 FL	*88.79 FL
34	1		*REAR WINDSCREEN BOTTOM MOULDING	Necessary	65.42 FL	*65.42 FL
35	1		*FRONT BONNET	Bent	663.55 FL	*663.55 FL
36	1		*FRONT BONNET HINGE LH	Distorted	74.77 FL	*74.77 FL
37	1		*FRONT BONNET HINGE RH	Distorted	74.77 FL	*74.77 FL
38	1		*FRONT BONNET STRUT LH	Serviceable	52.34 FL	*- FL
39	1		*FRONT BONNET STRUT RH	Serviceable	52.34 FL	*- FL
40	1		*FRONT BONNET TESLA EMBLEM	Necessary	48.60 FL	*48.60 FL
41	1		*FRONT BONNET LOCK	Distorted	177.57 FL	*177.57 FL
42	1		*FRONT BONNET LOCK ACTUATOR ASSY	Serviceable	107.48 FL	*- FL
43	1		*FRONT BONNET STRIKER	Distorted	2.80 FL	*2.80 FL
44	1		*FRONT LUGGAGE COMPARTMENT	Distorted	64.49 FL	*64.49 FL
45	1		*FRONT LUGGAGE COMPARTMENT MAT	Distorted	74.77 FL	*74.77 FL
46	1		*FRONT HEADLAMP LH	Serviceable	1,308.41 FL	*- FL
47	1		*FRONT HEADLAMP RH	Cracked	1,308.41 FL	*1,307.88 FL
48	1		*FRONT HEADLAMP LOWER BRACKET LH	Serviceable	7.48 FL	*- FL
49	1		*FRONT HEADLAMP LOWER BRACKET RH	Serviceable	7.48 FL	*- FL
50	1		*FRONT BUMPER	Torn	663.55 FL	*663.55 FL
51	1		*FRONT BUMPER SIDE BRACKET LH	Serviceable	9.35 FL	*- FL
52	1		*FRONT BUMPER SIDE BRACKET RH	Distorted	9.35 FL	*9.35 FL
53	1		*FRONT BUMPER CENTER UPPER BRACKET LH	Serviceable	12.15 FL	*- FL
54	1		*FRONT BUMPER CENTER UPPER BRACKET RH	Bent	12.15 FL	*12.15 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1		*FRONT BUMPER LOWER GRILLE	Cracked	102.80 FL	*102.80 FL
56	1		*FRONT BUMPER REINFORCEMENT	Bent	271.03 FL	*271.03 FL
57	1		*FRONT BUMPER ABSORBER FOAM	Cracked	46.73 FL	*46.73 FL
58	1		*FRONT BUMPER REINFORCEMENT CRUSH CAN LH	Serviceable	52.34 FL	*- FL
59	1		*FRONT BUMPER REINFORCEMENT CRUSH CAN RH	Bent	52.34 FL	*52.34 FL
60	1		*FRONT BUMPER LOWER REINFORCEMENT	Repair	102.80 FL	*- FL
61	1		*FRONT BUMPER LOWER REINFORCEMENT CRUSH CAN LH	Serviceable	59.81 FL	*- FL
62	1		*FRONT BUMPER LOWER REINFORCEMENT CRUSH CAN RH	Serviceable	59.81 FL	*- FL
63	1		*FRONT SUPPORT BEAM	Cracked	738.32 FL	*738.32 FL
64	1		*FRONT SUPPORT BEAM BRACKET LH	Serviceable	7.48 FL	*- FL
65	1		*FRONT SUPPORT BEAM BRACKET RH	Distorted	7.48 FL	*7.48 FL
66	1		*FRONT BUMPER UNDER COVER	Serviceable	186.92 FL	*- FL
67	6		*FRONT BUMPER PARKING SENSOR	Shorted (2 PCS ONLY)	953.28 FL	*317.76 FL
68	1		*FRONT BUMPER PARKING SENSOR BRACKET (6 PCS)	Necessary (2 PCS ONLY)	28.02 FL	*9.34 FL
69	1		*FRONT RADAR SENSOR	Dented	345.79 FL	*345.79 FL
70	1		*FRONT RADAR SENSOR BRACKET	Repair	4.67 FL	*- FL
71	1		*FRONT RADAR SENSOR SUPPORT BRACKET	Bent	7.48 FL	*7.48 FL
72	1		*FRONT FENDER RH	Buckled	448.60 FL	*448.60 FL
73	1		*FRONT FENDER INNER SHIELD RH	Serviceable	116.82 FL	*- FL
74	1		*FRONT DOOR RH (NPA)	Repair	0.00 FL	*- FL
75	1		*REAR BOOTLID INNER TRIM CLIPS	Necessary	50.00 FS	*50.00 FS
76	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
77	1		*REAR END PANEL JOINT SEALANT	Necessary	80.00 FS	*30.00 FS
78	1		*REAR FENDER QUARTER GLASS SEALANT RH	Necessary	60.00 FS	*30.00 FS
79	1		*REAR FENDER INNER SHIELD CLIPS RH	Necessary	40.00 FS	*40.00 FS
80	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
81	1		*REAR NUMBER PLATE & HOLDER	Distorted	50.00 FS	*45.00 FS
82	1		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
83	1		*FRONT FENDER INNER SHIELD CLIPS RH	Not Necessary	40.00 FS	*- FS
84	1		*REAR BOOTLID RUBBER GUIDE STOPPER RH	Necessary	1.87 FL	*1.87 FL
85	1		*REAR BOOTLID WEATHERSTRIP	Distorted	121.50 FL	*121.50 FL
86	1		*FRONT FENDER INNER BRACKET RH	Bent	23.36 FL	*23.36 FL
87	1		*FRONT BUMPER SIDE LAMP RH	Cracked	271.03 FL	*271.03 FL
88	1		*REAR BOOTLID LAMP LH	Cracked	177.57 FL	*177.57 FL
89	1		*REAR BUMPER WIRE HARDNESS	Cut	401.87 FL	*401.87 FL
90	1		*REAR TAILLAMP STOPPER RH	Necessary	12.15 FL	*12.15 FL
91	1		*A/C COMPRESSOR BRACKET	Cracked	29.91 FL	*29.91 FL
92	1		*FRONT NUMBER PLATE GARNISH	Dented	29.91 FL	*29.91 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,189.21	13,426.46
- List Item Discount on L Items 10.00/10.00% (\$)	1,766.92	1,307.15
Total Parts (\$)	16,422.29	12,119.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST ACCIDENT AREAS & ETC	New	3,000.00	1,700.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC	New	2,800.00	1,960.00
3	LABOUR CHARGES TO REMOVE & REPLACE FRONT & REAR PARKING SENSOR	New	200.00	120.00
4	LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM & UPHOLSTERY CUSHION SET & ETC .TO EFFECT REPLACE OF REAR FENDER RH	New	300.00	120.00
5	LABOUR CHARGES TO REMOVE & REPLACE REAR WINDSCREEN GLASS & ETC	New	200.00	120.00
6	LABOUR CHARGES TO REMOVE & REFIX REAR QUARTER GLASS LH & ETC	New	150.00	60.00
7	TO DAIGNOSIS FAULT CODE & RESET MEMORY	New	200.00	150.00
8	TO CHECK WIRING & ELECTRICAL SYSTEM ETC	New	120.00	40.00
9	TO TUFF KOTE & UNDERSEAL MATERIALS	New	250.00	60.00
Gross Labour Cost (S\$)			7,220.00	4,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >