5/9/22, 1:27 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22002960/BQY3N2

09/05/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMHCSNW00004132100

Claimant Vehicle

SLZ8906E

Insured

SMW1635L

Reg. Date:

No:

Vehicle No:

Date of Loss: 28/03/2022 Nature of Claim: TP Claim

SNM22D202146/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLZ8906E Reg No:

Make & Model: MAZDA 3, 1.5 SEDAN AT EU6 (A)

22/05/2018 (Man. Year: 2018)

Engine No: Chassis No: Odometer:

P520516018 JM6BN22A8J0224339

118692 km

Colour:

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16

Front Left Side: KAPSEN 5 mm Rear Left Side: INTERTRAC 5 mm Front Right Side: KAPSEN 5 mm Rear Right Side: INTERTRAC 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,701.13	1,212.16	2,488.97	67.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	660.00	2,640.00	80.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,001.13	1,872.16	5,128.97	73.26
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	7,001.13	1,500.00	5,501.13	78.57
+ GST 7.00/7.00% (S\$)	490.08	105.00	385.08	78.57
Nett Amount (S\$)	7,491.21	1,605.00	5,886.21	78.57

INSPECTION

Date of Assignment: 30/03/2022

160 SIN MING DR

#01-14 SIN MING AUTO CITY Date Inspected: 30/03/2022 Inspected At:

SINGAPORE 575722

REPAIRER: TEAM AUTOPRO PTE LTD

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

5/9/22, 1:27 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 May 2022)

Parts: 143 MAZDA 3 1.5 SEDAN AT EU6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLZ8906E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	1,496.70 FL	*757.80 FL
2	1		*REAR BUMPER REINFORCEMENT	Dented	684.20 FL	*326.40 FL
3	2		*REAR BUMPER REFLECTOR	Not Damaged	276.46 FL	*- FL
4	2		*REAR BUMPER TOW CAP	Not Damaged	82.00 FL	*- FL
5	1		*REAR END PANEL	Not Damaged	730.40 FL	*- FL
6	1		*REAR END PANEL TOP GARNISH	Not Damaged	109.40 FL	*- FL
7	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
8	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
9	2		*REAR BUMPER SIDE RETAINER	Necessary	217.80 FS	*114.80 FS
10	2		*REAR BUMPER REVERSE SENSOR	Short Circuit	500.00 FS	*200.00 FS
11	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
12	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
F=Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	4,376.96	1,429.00
			- List Item Discount on I	Litems 20.00/20.00% (S\$)	675.83	216.84
				Total Parts (S\$)	3,701.13	1,212.16
				_		

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
2	UPHOLSTERY	New	200.00	0.00
3	CHECK WIRING	New	100.00	0.00
4	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
5	PANEL BEATING	New	1,200.00	400.00
6	RUST PROOFING	New	200.00	0.00
7	SPRAY PAINTING	New	1,200.00	200.00
		Gross Labour Cost (S\$)	3,300.00	660.00
	Report was u	nsubmitted during this print-out.		

< END OF ESTIMATES >