

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22002964/VTY3E2

Date: 24/05/2022

REFERENCE

Insured/Claimant: LIN JINGQING Policy No: DMPCSNA00017042201
Date of Loss: 29/03/2022 Nature of Claim: OD Claim No: SNM22D202170/C01/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGQ7424S**
Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ2779504
Reg. Date: 23/01/2007 (Man. Year: 2006) Chassis No: ZNE100342441
Colour: Grey Odometer: 240079 km
Engine Capacity: 1794 cc
Market Value/New Car Price: S\$48,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45Z R17 Rear Tyre Size: 215/45Z R17
Front Left Side: Tourador 5 mm Rear Left Side: Tourador 5 mm
Front Right Side: Tourador 5 mm Rear Right Side: Tourador 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,347.00	3,291.00	56.00	1.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	541.80	461.00	80.80	14.91
Paintwork Labour	253.64	298.21	-44.57	-17.57
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,142.44	4,050.21	92.23	2.23
Approved Total (Overridden) (S\$)		3,250.00		
- Excess (S\$)	0.00	250.00	-250.00	
(S\$)	4,142.44	3,000.00	1,142.44	27.58
+ GST 7.00/7.00% (S\$)	289.97	210.00	79.97	27.58
Nett Amount (S\$)	4,432.41	3,210.00	1,222.41	27.58

INSPECTION

Date of Assignment: 30/03/2022 Present Location: Car City Auto Centre Pte Ltd (HQ)
Date Inspected: 31/03/2022 Inspected At: Car City Auto Centre Pte Ltd (HQ)
Estimated Period of Repair: 5.0 days Blk 9006 #01-198, Tampines Street 93
Singapore 528840

Adjuster: Thevan Thomas Karthikesavan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGQ7424S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BONNET	Dented	350.00 F	*350.00 F
2	1	NA	*BONNET MOULDING	Necessary	95.00 F	*95.00 F
3	1	NA	*CONDENSER	Bent	550.00 F	*550.00 F
4	1	NA	*FRONT BUMPER	Cut	190.00 F	*190.00 F
5	1	NA	*FRONT BUMPER SUPPORT	Dented	100.00 F	*100.00 F
6	1	NA	*FRONT PANEL CPL	Dented	330.00 F	*330.00 F
7	1	NA	*FRT BUMPER ABSORBER	Cut	60.00 F	*60.00 F
8	1	NA	*GRILLE	Cut	55.00 F	*55.00 F
9	1	NA	*INSULATION	Cut	160.00 F	*160.00 F
10	1	NA	*L/BONNET HINGE	Serviceable	28.00 F	*- F
11	1	NA	*L/F BUMPER BRACKET	Necessary	28.00 F	*28.00 F
12	1	NA	*L/F HEADLAMP	Cut	320.00 F	*320.00 F
13	1	NA	*LOCK CARRIER STRUT	Jammed	40.00 F	*40.00 F
14	1	NA	*LOWER BONNET LOCK	Jammed	40.00 F	*40.00 F
15	1	NA	*R/BONNET HINGE	Serviceable	28.00 F	*- F
16	1	NA	*R/F BUMPER BRACKET	Necessary	28.00 F	*28.00 F
17	1	NA	*R/F HEADLAMP	Cut	320.00 F	*320.00 F
18	1	NA	*RADIATOR CPL	Scratched	450.00 F	*450.00 F
19	1	NA	*RADIATOR SHROUD	Bent	75.00 F	*75.00 F
20	1	NA	*SUNDRY PARTS	Necessary	100.00 F	*100.00 F

F=Franchise part.

Total Parts (S\$)	3,347.00	3,291.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	176.40	197.40
2	Total Paint Materials	New	77.24	100.81
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	541.80	441.00
4	ANTI-FREEZE	New	-	20.00
Gross Labour Cost (\$)			795.44	759.21

Report was unsubmitted during this print-out.

< END OF ESTIMATES >