

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG22002965/EQY3N2**Date:** 04/05/2022**REFERENCE**

Insured/Claimant:	LIM GUAT LIU RUBY	Policy No:	1900260122-02	
Date of Loss:	07/03/2022	Nature of Claim:	OD	Claim No: 8523698542SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFN6047G		
Make & Model:	MITSUBISHI ASX, 2.0 (A)	Engine No:	4B11TR7086
Reg. Date:	26/10/2017 (Man. Year: 2017)	Chassis No:	JMFXTGA2WJZ000270
Colour:	Silver	Odometer:	42135 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$70,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,492.00	3,333.00	3,159.00	48.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,940.00	3,910.00	6,030.00	60.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,432.00	7,243.00	9,189.00	55.92
+ GST 7.00/7.00% (S\$)	1,150.24	507.01	643.23	55.92
Nett Amount (S\$)	17,582.24	7,750.01	9,832.23	55.92

INSPECTION

Date of Assignment:	30/03/2022	
Date Inspected:	31/03/2022 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	7.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$2,944.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE,RR BUMPER	Broken	745.00 F	*745.00 F
2	1		*BRKT,R/BMPR FACE SUPT,LH	*Check	22.00 F	*- F
3	1		*BRKT,R/BMPR FACE SUPT,RH	Broken	22.00 F	*22.00 F
4	2		*BRACKET,RR BUMPER	*Check	34.00 F	*- F
5	1		*REINFORCEMENT,RR BUMPER	Dented	234.00 F	*234.00 F
6	8		*CLIP,ENG ROOM COVER	Necessary	16.00 F	*16.00 F
7	1		*GARNISH,RR BUMPER,CTR	Missing	18.00 F	*18.00 F
8	1		*REFLECTOR,LH	Not Necessary	104.00 F	*- F
9	1		*REFLECTOR,RH	Broken	104.00 F	*104.00 F
10	1		*TRIM,RR END	Crushed	123.00 F	*123.00 F
11	1		*PANEL,RR END	Dented	261.00 F	*261.00 F
12	1		*W/STRIP,TAILGATE OPENING	Crushed	194.00 F	*194.00 F
13	2		*HINGE,TAILGATE	Not Necessary	56.00 F	*- F
14	1		*LATCH,TAILGATE	*Check	385.00 F	*- F
15	1		*STRIKER,TAILGATE LATCH	Not Necessary	19.00 F	*- F
16	1		*GARNISH,TAILGATE	Crushed	129.00 F	*129.00 F
17	2		*STOPPER,WINDSHIELD GLASS	Necessary	6.00 F	*6.00 F
18	2		*SPACER,TAILGATE	Necessary	6.00 F	*6.00 F
19	4		*FASTENER,WINDSHIELD	Necessary	24.00 F	*24.00 F
20	1		*GAS SPRING,TAILGATE,LH	Not Necessary	148.00 F	*- F
21	1		*GAS SPRING,TAILGATE,RH	Not Necessary	148.00 F	*- F
22	1		*MARK,THREE-DIA	Necessary	61.00 F	*61.00 F
23	1		*MARK,ASX	Necessary	56.00 F	*56.00 F
24	1		*LAMP ASSY,COMB,RR LH	Not Necessary	560.00 F	*- F
25	1		*LAMP ASSY,COMB,RR RH	Broken	560.00 F	*560.00 F
26	1		*LAMP ASSY,TAIL,LH	Cracked	177.00 F	*177.00 F
27	1		*LAMP ASSY,TAIL,RH	Broken	177.00 F	*177.00 F
28	2		*LAMP ASSY,LICENSE PLATE	*Check	68.00 F	*- F
29	1		*MOTOR,RR WINDOW WIPER	*Check	454.00 F	*- F
30	1		*MOULDING,RR WHEEL ARCH,LH	*Check	132.00 F	*- F
31	1		*MOULDING,RR WHEEL ARCH,RH	*Check	132.00 F	*- F
32	1		*PROT,UNDER RR FLOOR HEAT	*Check	81.00 F	*- F
33	1		*MUFFLER,EXHAUST MAIN	*Check	637.00 F	*- F
34	2		*HANGER,EXHAUST MUFFLER	*Check	48.00 F	*- F
35	1		*GASKET,CATALYTIC CONVERTER	*Check	11.00 F	*- F
36	1		*C&C BADGE	Necessary	50.00 FS	*50.00 FS
37	1		*SUNDRIES	Necessary	80.00 FS	*20.00 FS
38	1		*BODY PNL SEALANT	Necessary	80.00 FS	*80.00 FS
39	1		*REVERSE SENSOR	Shorted	250.00 FS	*220.00 FS
40	1		*RR NUMBER PLATE WITH CASING	Cut	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **6,492.00** **3,333.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW TAILGATE,RR BUMPER & RR END PNL.REPAIR RR FLR PNL,LHR FENDER & RHR FENDER	New	4,500.00	1,800.00
2	RESPRAY TAILGATE,RR BUMPER,RR END PNL,RR FLR PNL,LHR FENDER & RHR FENDER	New	3,300.00	1,400.00
3	REMOVE & REFIT TAILGATE COMPONENT	New	300.00	120.00
4	REMOVE & REFIT RR EXHAUST MUFFLER *Check	New	640.00	0.00
5	REMOVE & REFIT RR FLR BOARD TRIM & CARPET *Check	New	300.00	0.00
6	CHECK WIRING ELECTRICAL SYSTEM	New	80.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	120.00
8	REMOVE & REFIT RR WINDSCREEN GLASS	New	240.00	240.00
9	SUPPLY WINDSCREEN SEALANT	New	80.00	80.00
10	REMOVE & REFIT REVERSE SENSOR	New	100.00	80.00
11	APPLY ANTI CORROSION ON AFFECTED AREAS	New	120.00	40.00
Gross Labour Cost (\$\$)			9,940.00	3,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >