



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 3246P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BUCKLED	780.00	565.70
1	TAIL LAMP (R)	CUT / CRACKED	340.00	340.00
1	TAIL LAMP CLIPS (R)	NECESSARY	50.00	50.00
1	TAIL LAMP PANEL (R)	TO REPAIR SEE LABOUR	179.00	-
2	REAR BUMPER RETAINER L/R @\$65.80	O/S DISTORTED / N/S NOT NECESSARY	131.60	65.80
2	REAR BUMPER REFLECTOR L/R @\$112.00	SERVICEABLE	224.00	-
	LESS 25% DISCOUNT		-426.15	-255.38
			1,278.45	766.12
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER REVERSE SENSOR (SN)	SCRATCHED	280.00	200.00
1	TAIL LAMP CLIPS (R) (SN)	NOT NECESSARY	50.00	-
1	TAIL LAMP PANEL SEALANT (SN)	NOT NECESSARY	120.00	-
1	END PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	REAR FENDER SEALANT (SN)	NOT NECESSARY	180.00	-
			758.00	248.00
<u>LABOUR</u>				
	TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED, DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING.		280.00	20.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		80.00	50.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS, TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF TAIL LAMP PANEL (R).		880.00	320.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACE, FINAL POLISING AND WAXING ARE ALSO AVAILABLE. END PANEL SEALANT.		730.00	400.00

Report Ref No. CS/SMO22002966/Kqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.	NOT NECESSARY	120.00	-
			2,090.00	790.00
GRAND TOTAL			4,126.45	1,804.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,450.00

Report Ref No. CS/SMO22002966/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.