

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002967/APA3Q2**Date:** 04/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100489394
Claimant Vehicle No :	SMK3006C	Insured Vehicle No :	SGN5290P
Date of Loss:	28/03/2022	Nature of Claim:	TP
		Claim No:	6993402047SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK3006C	Engine No:	2NRX433097
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR2B23F3701171353
Reg. Date:	03/04/2019 (Man. Year: 2019)	Odometer:	86472 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,583.57	9,778.32	5,805.25	37.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,290.00	3,600.00	3,690.00	50.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,873.57	13,378.32	9,495.25	41.51
Approved Total (Overridden) (S\$)		10,700.00		
(S\$)	22,873.57	10,700.00	12,173.57	53.22
+ GST 7.00/7.00% (S\$)	1,601.15	749.00	852.15	53.22
Nett Amount (S\$)	24,474.72	11,449.00	13,025.72	53.22
+ Loss of Use (13.0 x S\$60.00/day) (S\$)		780.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		12,236.45		
Global Sum Settlement (S\$)		12,200.00		

INSPECTION

Date of Assignment:	29/03/2022	MG Solution Pte Ltd (HQ)
Date Inspected:	29/03/2022 Inspected At:	23 Kaki Bukit Avenue 4 #02-03B, VICOM
		Inspection Centre
		Singapore 415933
Estimated Period of Repair:	12.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	850.30 FL	*850.30 FL
2	2		*BONNET HINGE	Bent	124.60 FL	*124.60 FL
3	1		*BONNET LOCK	Damaged	180.20 FL	*180.20 FL
4	1		*BONNET LOCK BRACE PANEL	Bent	120.00 FL	*120.00 FL
5	1		*FRONT BUMPER	Deformed	520.50 FL	*520.50 FL
6	2		*FRONT BUMPER SIDE RETAINER	Necessary	85.00 FL	*85.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Dented	350.00 FL	*350.00 FL
8	1		*FRONT BUMPER FOGLAMP	Not Necessary	255.60 FL	*- FL
9	1		*FRONT BUMPER FOGLAMP COVER	Not Necessary	90.00 FL	*- FL
10	1		*FRONT LOWER GRILLE	Deformed	320.50 FL	*269.00 FL
11	1		*FRONT LOWER GRILLE TOWING COVER	Deformed	50.00 FL	*50.00 FL
12	2		*FRONT LOWER GRILLE SIDE GARNISH	Deformed	160.00 FL	*160.00 FL
13	1		*FRONT GRILLE	Cracked	320.50 FL	*320.50 FL
14	1		*FRONT GRILLE LOGO	Necessary	90.00 FL	*90.00 FL
15	1		*FRONT GRILLE LOGO HOUSING	Cracked	155.30 FL	*155.30 FL
16	2		*FRONT GRILLE SIDE GARNISH	Not Necessary	110.40 FL	*- FL
17	1		*FRONT GRILLE RUBBER	Cut	40.00 FL	*40.00 FL
18	2		*FRONT FENDER	Repair	1,160.60 FL	*- FL
19	2		*HORN	Not Necessary	180.00 FL	*- FL
20	2		*HEADLAMP	Cracked	1,021.60 FL	*1,021.60 FL
21	1		*FRONT SUPPORT PANEL	Buckled	1,130.50 FL	*891.00 FL
22	1		*FRONT SUPPORT PANEL COVER	Deformed	133.20 FL	*133.20 FL
23	1		*RADIATOR	Cracked	850.50 FL	*850.50 FL
24	2		*RADIATOR SIDE PROTECTOR	Deformed	111.20 FL	*111.20 FL
25	1		*RADIATOR SIDE COVER	Deformed	90.00 FL	*90.00 FL
26	1		*AIR CONDENSOR	Dented	620.50 FL	*620.50 FL
27	1		*AIR CONDENSOR FAN HOUSING BLADE	Cracked	125.50 FL	*125.50 FL
28	1		*AIR CONDENSOR FAN HOUSING	Cracked	320.50 FL	*244.00 FL
29	1		*AIR CONDENSOR FAN HOUSING MOTOR	Damaged	420.00 FL	*420.00 FL
30	1		*COOLANT SPARE TANK	Not Necessary	280.50 FL	*- FL
31	1		*AIR DUCT	Necessary	166.50 FL	*90.00 FL
32	1		*AIR CLEANER BOX	Cracked	188.50 FL	*188.50 FL
33	1		*BOOTLID VIOS EMBLEM	Repeated	58.60 FL	*- FL
34	1		*BOOTLID	Buckled	1,055.20 FL	*838.00 FL
35	1		*BOOTLID LOGO	Necessary	80.00 FL	*80.00 FL
36	1		*BOOTLID VIOS EMBLEM	Necessary	58.60 FL	*58.60 FL
37	1		*BOOTLID E EMBLEM	Necessary	65.20 FL	*65.20 FL
38	2		*BOOTLID REFLECTOR	Not Necessary	640.00 FL	*- FL
39	1		*BOOTLID TOP LOCK	Damaged	155.20 FL	*155.20 FL
40	1		*BOOTLID LOWER CATCH	Not Necessary	87.00 FL	*- FL
41	1		*BOOTLID WEATHERSTRIP	Cut	188.50 FL	*188.50 FL
42	1		*BOOTLID REFLECTOR	Cracked	157.00 FL	*157.00 FL
43	1		*REAR BUMPER	Deformed	620.20 FL	*522.00 FL
44	2		*REAR BUMPER SIDE RETAINER	Necessary	124.80 FL	*124.80 FL
45	1		*REAR BUMPER REINFORCEMENT	Dented	422.30 FL	*316.00 FL
46	2		*REAR BUMPER REFLECTOR	Not Necessary	181.20 FL	*- FL
47	2		*TAIL LAMP	Cracked	910.40 FL	*910.40 FL
48	2		*TAIL LAMP PANEL	Repair	466.20 FL	*- FL
49	2		*TAIL LAMP LOWER BRACKET	Not Necessary	160.40 FL	*- FL
50	2		*REAR FENDER	Repair	1,960.40 FL	*- FL
51	2		*REAR FENDER INNER TRIM	Not Necessary	710.40 FL	*- FL
52	1		*REAR END PANEL	Dented	708.00 FL	*708.00 FL
53	1		*REAR END PANEL TOP GARNISH	Deformed	146.00 FL	*146.00 FL
54	1		*FRONT NUMBER PLATE	Dented	50.00 FS	*50.00 FS
55	1		*SET FRONT BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SET FRONT GRILLE CLIP	Necessary	20.00 FS	*20.00 FS
57	1		*SET FRONT FENDER COWLING CLIPS	Not Necessary	20.00 FS	*- FS
58	1		*SET SUPPORT PANEL COVER CLIP	Necessary	20.00 FS	*20.00 FS
59	1		*RADIATOR COOLANT	Necessary	80.00 FS	*40.00 FS
60	1		*REAR BUMPER PLATE	Dented	50.00 FS	*50.00 FS
61	1		*BOOTLID SEALANT	Not Necessary	80.00 FS	*- FS
62	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
63	2		*TAILLAMP PANEL SEALANT	Not Necessary	160.00 FS	*- FS
64	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	20.00 FS	*- FS
65	1		*REAR END PANEL INSULATION SEAL	Necessary	120.00 FS	*60.00 FS
66	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
67	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	20,478.10	12,871.10
- List Item Discount on L Items 25.00/25.00% (\$)	4,894.53	3,092.78
Total Parts (\$)	15,583.57	9,778.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING REMOVING AND REPLACING PARTS	New	1,200.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	800.00
3	WIRING CHECK	New	150.00	30.00
4	REMOVE AND REFILL AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	60.00
5	REMOVE AND REFILL RADIATOR AND CONDUCT PRESSURE TEST	New	100.00	60.00
6	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,800.00	800.00
7	SPRAY PAINTING TO AFFECTED AREA	New	1,800.00	800.00
8	TUFF COAT	New	180.00	60.00
9	TO CONDUCT WATER LEAKAGE TEST	New	250.00	0.00
10	WIRING CHECK	New	150.00	30.00
11	TRANSFER BOOTLID MECHANISM	New	120.00	60.00
12	REMOVE AND REFILL REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
13	REMOVE AND REFILL REAR WINDSCREEN	New	80.00	0.00
14	REMOVE AND REFILL REVERSE CAMERA AND DISTANCE SETTING	New	60.00	50.00
Gross Labour Cost (\$\$)			7,290.00	3,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >