

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002968/APA3Q2**Date:** 28/04/2023REFERENCE

| | | | |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 2100450297 |
| Claimant Vehicle No : | GBL5675H | Insured Vehicle No : | SDL9698S |
| Date of Loss: | 28/03/2022 | Nature of Claim: | TP |
| | | Claim No: | 8746430327SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|---------------|
| Reg No: | GBL5675H | Engine No: | 1GD8710824 |
| Make & Model: | TOYOTA HIACE, 2.8 D DX (A) | Chassis No: | GDH2012018684 |
| Reg. Date: | 27/10/2021 (Man. Year: 2021) | Odometer: | 20815 km |
| Colour: | Silver | | |
| Engine Capacity: | 2754 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 195/80 R15 | Rear Tyre Size: | 195/80 R15 |
| Front Left Side: | Dunlop 6 mm | Rear Left Side: | Dunlop 6 mm |
| Front Right Side: | Dunlop 6 mm | Rear Right Side: | Dunlop 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 8,418.80 | 3,881.97 | 4,536.83 | 53.89 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,390.00 | 2,000.00 | 2,390.00 | 54.44 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 12,808.80 | 5,881.97 | 6,926.83 | 54.08 |
| Approved Total (Overridden) (S\$) | | 4,700.00 | | |
| Nett Amount (S\$) | 12,808.80 | 4,700.00 | 8,108.80 | 63.31 |
| + Loss of Use (6.0 x S\$80.00/day) (S\$) | | 480.00 | | |
| + Doc/Search Fee (S\$) | | 7.45 | | |
| Nett Liability (S\$) | | 5,187.45 | | |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|---|
| Date of Assignment: | 29/03/2022 | | |
| Date Inspected: | 29/03/2022 | Inspected At: | Kt Motorwerk (HQ) Blk 3012 Bedok Industrial Park E, #01-2020 Singapore 489978 |
| Estimated Period of Repair: | 6.0 days | | |

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|----------------------------------|---------------|------------|--------------|
| 1 | 1 | | *TAILGATE | Dented | 2,045.30 F | *2,045.30 FL |
| 2 | 1 | | *TAILGATE INNER BOARD | Not Necessary | 298.60 F | *- FL |
| 3 | 1 | | *TAILGATE OUTER GARNISH | Not Necessary | 365.80 F | *- FL |
| 4 | 1 | | *TAILGATE LOGO | Necessary | 98.70 F | *98.70 FL |
| 5 | 1 | | *TAILGATE HIACE STICKER | Necessary | 86.30 F | *45.00 FL |
| 6 | 1 | | *TAILGATE 1200KG STICKER | Necessary | 85.60 F | *48.00 FL |
| 7 | 1 | | *TAILGATE INNER LOCK | Damaged | 485.30 F | *358.00 FL |
| 8 | 1 | | *TAILGATE WEATHERSTRIP | Cut | 225.60 F | *225.60 FL |
| 9 | 1 | | *TAILGATE WINDSCREEN INNER SEAL | Necessary | 60.00 F | *60.00 FL |
| 10 | 1 | | *TAILGATE WINDSCREEN MOLDING | Necessary | 185.60 F | *185.60 FL |
| 11 | 1 | | *TAILLAMPS | N/S Cracked | 771.20 F | *385.60 FL |
| 12 | 1 | | *REAR CORNER BUMPER | N/S Deformed | 397.20 F | *198.60 FL |
| 13 | 2 | | *REAR CORNER BUMPER RETAINERS | Not Necessary | 197.20 F | *- FL |
| 14 | 1 | | *REAR BUMPER | Deformed | 485.60 F | *485.60 FL |
| 15 | 1 | | *REAR BUMPER RETAINERS | N/S Damaged | 197.20 F | *65.00 FL |
| 16 | 2 | | *REAR FENDER AIRDUCT | Not Necessary | 151.20 F | *- FL |
| 17 | 1 | | *END PANEL OUTER | Dented | 468.30 F | *468.30 FL |
| 18 | 1 | | *END PANEL INNER | Repair | 498.60 F | *- FL |
| 19 | 1 | | *END PANEL TOP PLATE | Not Necessary | 356.90 F | *- FL |
| 20 | 1 | | *FLOOR PANEL VINYL MAT | Not Necessary | 398.60 F | *- FL |
| 21 | 1 | | *REAR NUMBER PLATE WITH CASING | Not Necessary | 50.00 FS | *- FS |
| 22 | 1 | | *SET REAR BUMPER CLIPS | Necessary | 30.00 FS | *30.00 FS |
| 23 | 1 | | *SET TAILGATE INNER BOARD CLIPS | Not Necessary | 30.00 FS | *- FS |
| 24 | 2 | | *SET TAILLAMPS CLIPS | Necessary | 60.00 FS | *30.00 FS |
| 25 | 1 | | *SET REAR WINDSCREEN SEALANT | Necessary | 80.00 FS | *60.00 FS |
| 26 | 1 | | *SET REAR BUMPER REVERSE SENSORS | Damaged | 250.00 FS | *200.00 FS |
| 27 | 1 | | *SET END PANEL SEALANT | Necessary | 60.00 FS | *60.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|-----------------|-----------------|
| Sub Total (\$\$) | 8,418.80 | 5,049.30 |
| - List Item Discount on L Items 0.00/25.00% (\$\$) | 0.00 | 1,167.33 |
| Total Parts (\$\$) | 8,418.80 | 3,881.97 |

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | PANEL BEATING | New | 1,800.00 | 800.00 |
| 2 | SPRAY PAINTING | New | 1,800.00 | 800.00 |
| 3 | CHECK WIRING ON TAILLAMP | New | 120.00 | 30.00 |
| 4 | ANTI RUST | New | 100.00 | 80.00 |
| 5 | REMOVE AND INSTALL REVERSE SENSOR | New | 120.00 | 50.00 |
| 6 | REMOVE AND INSTALL REAR TAILGATE AND MECHANISM | New | 150.00 | 80.00 |
| 7 | REMOVE AND INSTALL REAR TAILGATE WINDSCREEN | New | 150.00 | 120.00 |
| 8 | REMOVE AND INSTALL INTERIOR UPHOLSTERY | New | 150.00 | 40.00 |
| Gross Labour Cost (S\$) | | | 4,390.00 | 2,000.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >