9/20/22, 9:29 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22002969/AEA3Q2

Date: 20/09/2022

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100463195

Claimant Vehicle

Figure 4 Vehicle No. 2100463195

No: EV8882T Insured Vehicle No: SLB9375G

Date of Loss: 20/03/2022 Nature of Claim: TP Claim No: 2122391957SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: EV8882T

 Make & Model:
 OPEL INSIGNIA GRANDSPORT B15XHT, 1.5 (A)
 Engine No:
 B1172918HAKX0809

 Reg. Date:
 27/06/2018 (Man. Year: 2018)
 Chassis No:
 W0VZT6EB6J1070485

Colour: Black Odometer: 77434 km

Engine Capacity: 1490 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 245/45 R18
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm
Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		10,250.60	6,259.10	3,991.50	38.94
Miscellaneous Items		0.00	0.00	0.00	
Labour		6,160.00	1,230.00	4,930.00	80.03
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	16,410.60	7,489.10	8,921.50	54.36
	+ GST 7.00/7.00% (S\$)	1,148.74	524.24	624.50	54.36
	Nett Amount (S\$)	17,559.34	8,013.34	9,546.00	54.36

+ Car Rental (2.0 x S\$100.00/day) (S\$) 200.00

Nett Liability (S\$) 8,213.34

INSPECTION

Date of Assignment: 29/03/2022

Date Inspected: 29/03/2022 Inspected At: 1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01

Singapore 415933

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	1,900.00 FL	*1,900.00 FL
2	1		*SET FRT BUMPER GUIDE	Cracked	49.00 FL	*49.00 FL
3	1		*FRT BUMPER SUPPORT LEFT	Not Necessary	45.00 FL	*- FL
4	1		*FRT FENDER LH	Not Necessary	860.00 FL	*- FL
5	1		*FRT FENDER LINER LH	Not Necessary	280.00 FL	*- FL
6	1		*FRT HEADLIGHT LH	Cracked	4,950.00 FL	*4,950.00 FL
7	1		*FRT FOG LAMP LH	Not Necessary	430.00 FL	*- FL
8	1		*FRT BUMPER ABSORBER IMPACT LOWER	Not Necessary	160.00 FL	*- FL
9	1		*FRT BUMPER ABSORBER IMPACT	Not Necessary	720.00 FL	*- FL
10	1		*FRT BUMPER CENTRE SUPPORT	Not Necessary	250.00 FL	*- FL
11	1		*RH INSERT	Not Necessary	770.00 FL	*- FL
12	1		*LH INSERT	Not Necessary	770.00 FL	*- FL
13	1		*FLAP ,TOWING LUG ,FRT BUMPER	Not Necessary	150.00 FL	*- FL
14	1		*SET FRT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
F=Fra	nchise	part. S=SpcN	lett. L=ListItemDisc.	_		
				Sub Total (S\$)	11,384.00	6,949.00
			- List Item Discount on L I	tems 10.00/10.00% (S\$)	1,133.40	689.90
				Total Parts (S\$)	10,250.60	6,259.10
			Report was unsubmitted during	this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	3,200.00	650.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA (FRT BUMPER & FRT RH FENDER)	New	2,500.00	550.00
3	TO DISCONNECT WIRE HANRESS OF ELECTRICAL COMPOENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	150.00	30.00
4	TO CONDUCT 4 WHEEL ALIGNMENT	New	180.00	0.00
5	TO CONDUCT HEAD LIGHT ALIGNMENT	New	130.00	0.00
	Gross Labou	r Cost (S\$)	6,160.00	1,230.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >