## FIRST AUTOWORKS kepair Estimate

Date: 22/03/2022

To Whom It May Concern

Reference:

**EV 8882T** 

Make:

OPEL INSIGNIA

Dear Sir,

RE: VEHICLE .: EV 8882T

CHASSIS NO.: W0VZT6EB6J1070485 ENGINE NO.: B1172918HAKX0809

Total:

Labour Total:

10,200.60

6,160.00

Name of insured .: Twoon Kok Yam Date of accident.: 20/03/2022

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

| <b>Parts</b>   |     |   |              |                       |
|--|-----|---|--------------|-----------------------|
| No.  | Qty | Part Description  |              | Price (SGD)           |
| 1  | 1   | FRT BUMPER De d   |              | 1,900.00              |
|  | 1   | FRT BUMPER GUIDE LEFT FRT BUMPER SUPPORT LEFT MM FRT FENDER LH MM |              | 49.00                 |
| 3  | 1   | FRT BUMPER SUPPORT LEFT MM  |              | 45.00                 |
| 4  | 1   | FRT FENDER LH MM  |              | 860.00 <del>L</del> . |
| 5  | 1   | FRT FENDER LINER LH   |              | 280.00 ~              |
| 6  | 1   | FRT HEADLIGHT LH Could  |              | 4,950.00              |
| 7  | 1   | FRT FOG LAMP LH ANY ~   |              | 430.00 💸              |
| 8  | 1   | FRT BUMPER ABSORBER, IMPACT, LOWER 2                              |              | 160.00 +              |
| 9  | 1   | FRT BUMPER ABSORBER, IMPACT                                       | 6859         | 720.00 ×              |
| 10   | 1   | FRT BUMPER CENTRE SUPPORT   | 6209.10.     | 250.00 ~              |
| 11   | 1   | RH INSERT 2   | 6207.10.     | 770.00 イ              |
| 12   | 1   | LH INSERT (MELL   |              | 770.00 ×              |
| 2<br>3<br>4<br>5<br>6<br>7<br>8<br>9<br>10<br>11<br>12<br>13 | 1   | FLAP, TOWING LUG, FRT BUMPER HEM                                  |              | 150.00 ×              |
| 10   | •   |   |              | •                     |
|  |     |   | Parts Total: | 11,334.00             |
|  |     |   | Less 10%:    | 1.133.40              |

| <u>Labour</u><br><u>No.</u> | Labour Description   |                       | Price (SGD) |
|-----------------------------|--|-----------------------|-------------|
| 1                           | To dismantle / renew the accident damaged presenting, reshape, straighten, orientate and alignates.                            | n repair /replacement | 3200.00 650 |
| 2                           | Carry out spray painting on accident affected Frt RH Fender )  | area. ( Frt bumper &  | 2500.00 550 |
| <u>3</u>                    | To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair |                       | 150,00 30   |
| 4                           | To conduct 4 wheel alignment   | 1230                  | 180.00 ×    |
| <u>5</u>                    | To conduct head light alignment  |                       | 130.00 +    |

**Other** No.

· ITOMOTH

Other Description xac FRT BUMPER CLIP SET

50

Price (SGD) 50.00

Other Total:

50.00

Total:

\$16,410.60

Gst (7%):

\$1,148.74

**GRAND TOTAL:** 

\$17,559.34

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YO WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor Ronnie Tan

DID: 6844 1985 Fax:6844 5185

Adrian hing. P/P 29/03/22. 03 Days

total: 7489.10 (P/P)

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: