

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 780B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER REAR (DISC 25%)	DEFORMED	343.95	343.95
10	BUMPER CLIPS @ \$2.10 (DISC 25%)	NECESSARY	15.75	15.75
1	BUMPER REINFORCEMENT REAR	NOT NECESSARY	154.27	-
1	ARM SUB-ASSY, RR BUMPER RH	NOT NECESSARY	104.70	-
1	ARM SUB-ASSY, RR BUMPER RH	NOT NECESSARY	104.70	-
1	ANTENNA,ELECTRICAL LOWER REAR	NOT NECESSARY	141.66	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	BUMPER SIDE RETAINER RR/LH	NOT NECESSARY	71.10	-
1	BUMPER SIDE RETAINER RR/RH	NOT NECESSARY	71.10	-
1	BUMPER SEAL,RR LH	NOT NECESSARY	66.68	-
1	BUMPER SEAL,RR RH	NOT NECESSARY	49.28	-
1	BUMPER LIP COVER RR/LH	NOT NECESSARY	54.15	-
1	BUMPER LIP COVER RR/RH	NOT NECESSARY	88.57	-
1	BUMPER LIP REAR	NOT NECESSARY	171.68	-
1	END PANEL	NOT NECESSARY	451.58	-
			2,069.17	359.70
	<u>LABOUR</u>			
	PANEL BEATING & BODYWORK.		676.00	200.00
	SPRAY PAINT.		738.00	200.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	40.00
			1,794.00	440.00
	GRAND TOTAL		3,863.17	799.70





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		650.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC22002971/Rvcs2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

The

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser