

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22002977/KPA3Q2**Date:** 02/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993578
Claimant Vehicle No :	SHD9225T	Insured Vehicle No :	SMJ7093D
Date of Loss:	28/03/2022	Nature of Claim:	TP
		Claim No:	7252292587SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9225T		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2C08312
Reg. Date:	17/05/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FUX03079965
Colour:	Metallic Pearl White/Red	Odometer:	261526 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 7 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,003.87	1,531.52	6,472.35	80.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,710.00	805.00	4,905.00	85.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,713.87	2,336.52	11,377.35	82.96
+ GST 7.00/7.00% (S\$)	959.97	163.56	796.41	82.96
Nett Amount (S\$)	14,673.84	2,500.08	12,173.76	82.96
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$96.30/day) (S\$)		385.20		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,092.73		
Global Sum Settlement (S\$)		3,050.00		

INSPECTION

Date of Assignment:	30/03/2022		
Date Inspected:	30/03/2022	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.5 days		

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Buckled	442.60 FL	*442.60 FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Bent	332.70 FL	*332.70 FL
3	1		*COVER ,REAR BUMPER ,LOWER	Serviceable	15.40 FL	*- FL
4	1		*GUARD ,REAR BUMPER ,CENTER	Dented / Distorted	576.30 FL	*576.30 FL
5	1		*RETAINER ,REAR BUMPER SIDE ,LH	Serviceable	116.50 FL	*- FL
6	1		*RETAINER ,REAR BUMPER SIDE ,RH	Serviceable	117.70 FL	*- FL
7	1		*PANEL SUB-ASSY ,BACK DOOR	Repair	1,147.80 FL	*- FL
8	1		*GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	Repair	925.60 FL	*- FL
9	1		*WEATHERSTRIP BACK DOOR	Serviceable	372.30 FL	*- FL
10	1		*LENS & BODY ,REAR COMBINATION LAMP LH (UPPER)	Serviceable	443.30 FL	*- FL
11	1		*LENS AND BODY ,REAR LAMP ,LH (LOWER)	Serviceable	502.00 FL	*- FL
12	1		*LENS & BODY ,REAR COMBINATION LAMP ,RH (UPPER)	Serviceable	443.30 FL	*- FL
13	1		*LENS AND BODY ,REAR LAMP, RH (LOWER)	Serviceable	502.00 FL	*- FL
14	1		*COVER ,FLOOR UNDER ,NO .1 LH	Serviceable	175.10 FL	*- FL
15	1		*COVER ,FLOOR UNDER ,NO .2 RH	Serviceable	241.90 FL	*- FL
16	1		*COVER, REAR FLOOR CTR	Serviceable	229.90 FL	*- FL
17	1		*COVER, DECK TRIM ,REAR	Serviceable	126.70 FL	*- FL
18	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	650.30 FL	*- FL
19	1		*REAR TAILGATE TOYOTA LOGO	Necessary	47.90 FL	*47.90 FL
20	1		*REAR TAILGATE WORDING PRIUS	Necessary	54.60 FL	*54.60 FL
21	1		*REAR TAILGATE WORDING HYBRID	Necessary	54.60 FL	*54.60 FL
22	1		*SER PARKING AID	Shorted	700.00 FS	*220.00 FS
23	1		*SET REAR BUMPER CLIP	Necessary	95.00 FS	*60.00 FS
24	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
25	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
26	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS
27	1		*REAR TAILGATE STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
28	1		*REAR TAILGATE STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
29	1		*REAR BUMPER PROTECTOR	Not Necessary	180.00 FS	*- FS
30	2		*SEAM SEALANT	Not Necessary	250.00 FS	*- FS
31	1		*SET REAR BUMPER RETAINER CLIP	Not Necessary	85.00 FS	*- FS
32	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	140.00 FS	*- FS
33	1		*SET TAILLAMP LOWER CLIP	Not Necessary	55.00 FS	*- FS
34	1		*SET TAILLAMP UPPER CLIP	Not Necessary	55.00 FS	*- FS
35	1		*END PANEL TRIM CLIP	Not Necessary	65.00 FS	*- FS
36	1		*REAR BUMPER ADVERTISEMENT	Necessary	100.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,883.50	1,908.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,879.63	377.18
Total Parts (\$\$)	8,003.87	1,531.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,750.00	300.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
5	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	0.00
6	TO RUST PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
7	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,750.00	440.00
8	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
9	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
10	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
Gross Labour Cost (S\$)			5,710.00	805.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >