

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG22002982/ETY3E2

Date: 20/05/2022

REFERENCE

Insured/Claimant: ONG LAY HOON Policy No:
Date of Loss: 29/03/2022 Nature of Claim: OD Claim No: 5151285013SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH8634Y**
Make & Model: MITSUBISHI ATTRAGE, 1.2 (A) Engine No: 3A92UHL9319
Reg. Date: 13/02/2019 (Man. Year: 2018) Chassis No: MMBSTA13AKH000635
Colour: Red Odometer: 21470 km
Engine Capacity: 1193 cc
Market Value/New Car Price: S\$61,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,746.93	12,189.11	5,557.82	31.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,770.00	7,825.00	6,945.00	47.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,516.93	20,014.11	12,502.82	38.45
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	32,216.93	19,714.11	12,502.82	38.81
+ GST 7.00/7.00% (S\$)	2,255.19	1,379.99	875.20	38.81
Nett Amount (S\$)	34,472.12	21,094.10	13,378.02	38.81

INSPECTION

Date of Assignment: 31/03/2022
Date Inspected: 31/03/2022 Inspected At: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 12.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FR NUMBER PLATE WITH CASING	Broken	50.00 FS	*50.00 FS
2	1		*BODY PNL SEALANT	Necessary	80.00 FS	*40.00 FS
3	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
4	1		*FACE, FR BUMPER	Broken	811.00 FL	*811.00 FL
5	1		*COVER, FR BUMPER	Broken	12.00 FL	*16.00 FL
6	1		*COVER, HEADLAMP SUPT PANEL	Broken	62.00 FL	*62.00 FL
7	1		*GRILLE, FR UNDER	Broken	165.00 FL	*165.00 FL
8	1		*GARNISH, FR BUMPER, LH	Not Necessary	127.00 FL	*- FL
9	1		*GARNISH, FR BUMPER, RH	Not Necessary	127.00 FL	*- FL
10	1		*BRACKET, FR BUMPER, LH	Broken	13.00 FL	*13.00 FL
11	1		*BRACKET, FR BUMPER, RH	Broken	13.00 FL	*13.00 FL
12	5		*CLIP, FR BUMPER	Necessary	20.00 FL	*20.00 FL
13	1		*MARK, THREE-DIA	Necessary	70.00 FL	*70.00 FL
14	1		*GRILLE, RADIATOR	Broken	557.00 FL	*557.00 FL
15	1		*HOOD	Dented	737.00 FL	*737.00 FL
16	1		*HINGE, HOOD, LH	Bent	56.00 FL	*56.00 FL
17	1		*HINGE, HOOD, RH	Bent	56.00 FL	*56.00 FL
18	1		*INSULATOR, HOOD	Crushed	177.00 FL	*177.00 FL
19	2		*CLIP, HOOD INSULATOR	Necessary	18.00 FL	*6.00 FL
20	1		*LATCH, HOOD	Bent	69.00 FL	*69.00 FL
21	1		*FENDER, FR LH	Dented	500.00 FL	*500.00 FL
22	1		*FENDER, FR RH	Dented	500.00 FL	*500.00 FL
23	1		*SHIELD, FR WHEELHOUSE, LH	Not Necessary	98.00 FL	*- FL
24	1		*SHIELD, FR WHEELHOUSE, RH	Not Necessary	98.00 FL	*- FL
25	12		*CLIP, INNERSHIELD	Not Necessary	48.00 FL	*- FL
26	1		*PANEL ASSY, FR END	Dented	1,055.00 FL	*1,055.00 FL
27	1		*PANEL, HEADLAMP SUPPORT, UPR	Dented	66.00 FL	*66.00 FL
28	1		*PANEL, AIR GUIDE, LH	Broken	11.00 FL	*11.00 FL
29	1		*PANEL, AIR GUIDE, RH	Broken	11.00 FL	*11.00 FL
30	1		*COVER, ENG ROOM UNDER, FR	Not Necessary	99.00 FL	*- FL
31	1		*HEADLAMP ASSY, LH	Broken	663.00 FL	*663.00 FL
32	1		*HEADLAMP ASSY, RH	Broken	663.00 FL	*663.00 FL
33	1		*LAMP ASSY, FOG, FR LH	Not Necessary	305.00 FL	*- FL
34	1		*LAMP ASSY, FOG, FR RH	Not Necessary	305.00 FL	*- FL
35	1		*TANK, WINDSHIELD WASHER	Crushed	75.00 FL	*75.00 FL
36	1		*MOTOR, WINDSHIELD WASHER	Not Necessary	30.00 FL	*- FL
37	1		*GASKET, W/SHLF WASHER MOTOR	Not Necessary	4.00 FL	*- FL
38	1		*HARNESS, CONTROL	Not Necessary	1,245.00 FL	*- FL
39	1		*HARNESS, CHASSIS, FR	Not Necessary	1,487.00 FL	*- FL
40	1		*PANEL, AIR GUIDE	Broken	112.00 FL	*112.00 FL
41	1		*RADIATOR ASSY	Dented	972.00 FL	*972.00 FL
42	1		*TANK ASSY, RADIATOR COND	Crushed	42.00 FL	*42.00 FL
43	1		*FAN, COOLING	Broken	77.00 FL	*77.00 FL
44	1		*SHROUD, COOLING FAN	Broken	131.00 FL	*131.00 FL
45	1		*MOTOR, COOLING FAN	Broken	484.00 FL	*484.00 FL
46	1		*CONDENSER ASSY, A/C REFRIGE	Dented	762.00 FL	*762.00 FL
47	1		*SENSOR, AIR BAG, LH	Necessary	293.00 FL	*293.00 FL
48	1		*SENSOR, AIR BAG, LH	Not Necessary	293.00 FL	*- FL
49	1		*SPRING, AIR BAG SENSOR	Necessary	319.00 FL	*319.00 FL
50	1		*CONT UNIT, SRS DIAGNOSIS	Necessary	609.00 FL	*609.00 FL
51	1		*MODULE, AIR BAG	Necessary	600.00 FL	*600.00 FL
52	1		*MODULE, PASSENGER AIR BAG	Broken	1,672.00 FL	*1,672.00 FL
53	1		*PANEL, INSTRUMENT	Crushed	730.00 FL	*730.00 FL
54	1		*S/BELT, FR PRE-TENSIO, OTR L	Jammed	589.00 FL	*589.00 FL
55	1		*S/BELT, FR PRE-TENSIO, OTR R	Jammed	589.00 FL	*589.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*GARNISH, FR DECK	Not Necessary	178.00 FL	*- FL
57	1		*COVER, FR DECK, LH	Not Necessary	16.00 FL	*- FL
58	1		*COVER, FR DECK, RH	Not Necessary	16.00 FL	*- FL
59	1		*GARNISH, FR PILLAR, LH	Broken	30.00 FL	*30.00 FL
60	1		*GARNISH, FR PILLAR, RH	Broken	30.00 FL	*30.00 FL
61	1		*SEAT BELT, FR SEAT, INR LH	Not Necessary	93.00 FL	*- FL
62	1		*SEAT BELT, FR SEAT, INR RH	Not Necessary	102.00 FL	*- FL
63	1		*DUCT, A/CLNR INTAKE	Broken	131.00 FL	*131.00 FL
64	1		*BODY ASSY, AIR CLEANER	Not Necessary	153.00 FL	*- FL
65	1		*COVER, AIR CLEANER	Not Necessary	45.00 FL	*- FL
66	1		*INSULATOR, ENG MOUNTING	Not Necessary	205.00 FL	*- FL
67	1		*ROD ASSY, ENG ROLL STOPPER	Not Necessary	155.00 FL	*- FL
68	1		*INSULATOR, T/M MOUNTING	Not Necessary	209.00 FL	*- FL
69	2		*EMBLEM ECO	Necessary	34.00 FS	*34.00 FS
70	1		*UNPAINTED BODYKITS	Repair	1,643.00 FN	*- FL
71	1		*LLC 4L	Necessary	26.00 FL	*26.00 FL
72	1		*PIPE, A/C CONDENSER OUTLET (Supplementary)	Bent	305.00 FL	*305.00 FL
73	1		*HOSE, A/C COMPR DISCHARGE (Supplementary)	Bent	210.00 FL	*210.00 FL
74	1		*OIL COOLER ASSY, A/T (Supplementary)	Bent	558.00 FL	*558.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	22,926.00	15,787.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	4,850.47	3,597.89
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	328.60	0.00
Total Parts (\$\$)	17,746.93	12,189.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount	
Labour Items					
1	RESPRAY FR BUMPER, BODY KIT, BONNET, LHF FENDER, RHF FENDER, FR SUPPORT PNL, LHF DOOR, RHF DOOR, FR A PILLAR LH / RH & FR CHASSIS	New	4,200.00	3,500.00	
2	RENEW AC COND & RADIATOR	New	100.00	100.00	
3	TOP UP AC GAS	New	80.00	80.00	
4	RENEW DASHBOARD ASSY. REMOVE & REFIT INSTRUMENT PNL, CENTER CLUSTER & RADIO	New	900.00	900.00	
5	REMOVE & REFIT ENGINE & GEARBOX ASSY	New	1,350.00	0.00	
6	RENEW DRIVER AIRBAG, PASSENGER AIRBAG, SENSOR & AIRBAG CONTROL UNIT	New	900.00	450.00	
7	RENEW FRT SAFETY BELT & BUCKLE LH / RH	New	450.00	275.00	
8	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00	
9	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00	
10	CONDUCT CHASSIS ALIGNMENT - CELETTE BENCH	New	1,000.00	0.00	
11	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	0.00	
12	APPLY ANTI CORROSION ON AFFECTED AREAS	New	120.00	40.00	
13	RENEW FR BUMPER, BODY KIT, BONNET, LHF FENDER, RHF FENDER & FR SUPPORT PNL. REPAIR LHF DOOR, RHF DOOR & FR A PILLAR LH / RH	New	5,400.00	2,330.00	
			Gross Labour Cost (\$\$)	14,770.00	7,825.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >