

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002990/AQY3S2**Date:** 26/05/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00238222102

**Claimant Vehicle
No :** SMH3687C**Insured Vehicle
No :** SLV3240X

Date of Loss: 30/03/2022

Nature of Claim: TP

Claim
No: SNM22D202209/C02/TANKL**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMH3687C**Make & Model: MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED)
(A)

Engine No: 27491031199492

Reg. Date: 30/01/2018 (Man. Year: 2017)

Chassis No: WDD2050402R351787

Colour: Silver

Odometer: 83656 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35 R19

Rear Tyre Size: 245/35 R19

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,190.20	11,083.90	14,106.30	56.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,270.00	2,440.00	3,830.00	61.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,460.20	13,523.90	17,936.30	57.01
Approved Total (Overridden) (S\$)		10,800.00		
Nett Amount (S\$)	31,460.20	10,800.00	20,660.20	65.67

INSPECTION

Date of Assignment: 31/03/2022

Date Inspected: 31/03/2022 Inspected At:

HD Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 May 2022)

Parts: 143 MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMH3687C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	2,191.00 FL	*1,831.00 FL
2	1	*REAR BUMPER CENTRE FRAME	Cracked	232.00 FL	*232.00 FL
3	1	*REAR BUMPER TOWING COVER	Not Necessary	88.00 FL	*- FL
4	1	*REAR BUMPER EXHAUST COVER GARNISH	Cracked	138.00 FL	*138.00 FL
5	1	*REAR BUMPER REVERSE SENSOR (6pcs)	Damaged 2pcs Only	1,590.00 FL	*530.00 FL
6	6	*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	402.00 FL	*120.00 FL
7	1	*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	798.00 FL	*- FL
8	2	*REAR BUMPER CENTER UPPER BRACKET	Not Necessary	156.00 FL	*- FL
9	1	*REAR BUMPER BOTTOM CENTER GARNISH	Deformed	185.00 FL	*185.00 FL
10	1	*REAR BUMPER LOWER GARNISH	Deformed	285.00 FL	*285.00 FL
11	1	*REAR BUMPER LOWER GARNISH CHROME	Cracked	346.00 FL	*346.00 FL
12	2	*REAR BUMPER UPPER CORNER BRACKET	Not Necessary	358.00 FL	*- FL
13	2	*REAR BUMPER SIDE RETAINER	Necessary	148.00 FL	*148.00 FL
14	2	*REAR BUMPER LOWER BRACKET (CENTER)	Cracked	130.00 FL	*130.00 FL
15	1	*REAR BUMPER SMART SENSOR CONTROL UNIT	Cracked	374.00 FL	*374.00 FL
16	1	*REAR BUMPER SMART SENSOR	Necessary	169.00 FL	*- FL
17	1	*REAR BUMPER SMART SENSOR MOTOR C/W CABLE	Not Necessary	279.00 FL	*- FL
18	1	*REAR BUMPER REINFORCEMENT	Dented	658.00 FL	*658.00 FL
19	2	*REAR FENDER DRAIN GARNISH	Not Necessary	196.00 FL	*- FL
20	2	*REAR FENDER COWLING	Not Necessary	396.00 FL	*- FL
21	2	*REAR FENDER INNER TRIM	Not Necessary	850.00 FL	*- FL
22	2	*TAILLAMP	Cracked	1,524.00 FL	*1,524.00 FL
23	2	*TAILLAMP PANEL	Not Necessary	1,972.00 FL	*- FL
24	1	*BOOTLID	Dented	2,450.00 FL	*2,323.00 FL
25	1	*BOOTLID REVERSE CAMERA	Not Necessary	1,650.00 FL	*- FL
26	1	*BOOTLID CENTER MOULDING	Necessary	159.00 FL	*159.00 FL
27	1	*BOOTLID LOGO	Necessary	48.00 FL	*48.00 FL
28	1	*BOOTLID OUTER SWITCH BUTTON	Not Necessary	183.00 FL	*- FL
29	1	*BOOTLID EMBLEM C200	Necessary	86.00 FL	*86.00 FL
30	1	*BOOTLID EMBLEM 9G-TRONIC	Necessary	86.00 FL	*86.00 FL
31	4	*BOOTLID STOPPER	Not Necessary	180.00 FL	*- FL
32	2	*BOOTLID HINGE	Not Necessary	262.00 FL	*- FL
33	1	*BOOTLID INSULATOR	Not Necessary	598.00 FL	*- FL
34	1	*BOOTLID TOP LOCK	Damaged	300.00 FL	*300.00 FL
35	1	*BOOTLID LOWER LOCK	Not Necessary	48.00 FL	*- FL
36	1	*BOOTLID WEATHERSTRIP	Cut	189.00 FL	*189.00 FL
37	1	*BOOTLID NUMBER PLATE LAMP GARNISH	Not Necessary	168.00 FL	*- FL
38	1	*REAR END PANEL	Dented	1,460.00 FL	*1,260.00 FL
39	1	*REAR END PANEL INNER GARNISH	Deformed	285.00 FL	*285.00 FL
40	1	*REAR WELL PANEL TRIM	Not Necessary	328.00 FL	*- FL
41	1	*REAR FLOOR PANEL (WELL PANEL)	Cracked	986.00 FL	*686.00 FL
42	1	*REAR FLOOR PANEL SPONGE	Not Necessary	190.00 FL	*- FL
43	1	*REAR FLOOR PANEL COVER BOARD	Not Necessary	649.00 FL	*- FL
44	1	*REAR FLOOR UNDER SIDE GARNISH RH	Cracked	248.00 FL	*248.00 FL
45	1	*REAR EXHAUST BOX	Not Necessary	1,630.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	2		*REAR EXHAUST INSULATOR	Not Necessary	392.00 FL	*- FL
47	4		*REAR EXHAUST MOUNTING	Not Necessary	388.00 FL	*- FL
48	2		*REAR EXHAUST MOUNTING BRACKET	Not Necessary	150.00 FL	*- FL
49	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
50	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
51	1		*SET REAR BUMPER BOTTOM CENTER GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
52	1		*SET REAR BUMPER LOWER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
53	1		*SET REAR BUMPER EXHAUST COVER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
54	1		*BOOTLID SEALANT	Not Necessary	150.00 FS	*- FS
55	1		*SET BOOTLID INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
56	1		*BOOTLID CENTER MOULDING CLIP	Not Necessary	50.00 FS	*- FS
57	1		*SET BOOTLID NUMBER PLATE LAMP GARNISH CLIP	Not Necessary	50.00 FS	*- FS
58	1		*SET TAILLAMP CLIP	Necessary	50.00 FS	*- FS
59	1		*SET REAR FENDER DRAIN GARNISH CLIP	Not Necessary	80.00 FS	*- FS
60	1		*SET REAR FENDER COWLING CLIP	Not Necessary	50.00 FS	*- FS
61	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
62	1		*REAR END PANEL INSULATOR SEAL	Necessary	150.00 FS	*60.00 FS
63	1		*SET REAR END PANEL INNER GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
64	1		*REAR FLOOR PANEL SEALANT	Not Necessary	180.00 FS	*- FS
65	1		*SET REAR FLOOR UNDER SIDE GARNISH CLIP RH	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	27,848.00	12,301.00
- List Item Discount on L Items 10.00/10.00% (\$)	2,657.80	1,217.10
Total Parts (\$)	25,190.20	11,083.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS.	New	1,800.00	1,100.00
2	TO SPRAY PAINT AFFECTED AREA.	New	1,600.00	800.00
3	TUFF COAT.	New	350.00	80.00
4	WIRING CHECK.	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT / UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR.	New	380.00	60.00
6	TRANSFER BOOTLID MECHANISM.	New	80.00	60.00
7	CONDUCT WATER LEAKAGE TEST.	New	100.00	0.00
8	REMOVE AND REFIX AND RESET BOOTLID AUTO SYSTEM.	New	250.00	0.00
9	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.	New	280.00	50.00
10	REMOVE AND REFIX REAR EXGHAUST PIPE.	New	350.00	80.00
11	REAR CHASSIS ALIGNMENT.	New	250.00	0.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	New	650.00	180.00
Gross Labour Cost (\$\$)			6,270.00	2,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >