

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002995/KTY3N2**Date:** 24/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00002682101

Claimant Vehicle No : SNE3041U **Insured Vehicle No :** SMC5169U

Date of Loss: 25/03/2022 Nature of Claim: TP Claim No: SNM22D202133/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNE3041U**

Make & Model: TOYOTA COROLLA, 1.5 (A) Engine No: 2ZRY788814

Reg. Date: 03/03/2022 (Man. Year: 2021) Chassis No: MR2BZ3BE700008646

Colour: Metallic Silver Odometer: 3409 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17

Front Left Side: Michelin 9 mm Rear Left Side: Michelin 9 mm

Front Right Side: Michelin 9 mm Rear Right Side: Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,747.25	2,766.50	1,980.75	41.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,360.00	1,440.00	920.00	38.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,107.25	4,206.50	2,900.75	40.81
Approved Total (Overridden) (\$\$)		3,350.00		
(\$\$)	7,107.25	3,350.00	3,757.25	52.87
+ GST 7.00/7.00% (\$\$)	497.51	234.50	263.01	52.87
Nett Amount (\$\$)	7,604.76	3,584.50	4,020.26	52.87

INSPECTION

Date of Assignment: 31/03/2022

Date Inspected: 30/03/2022 Inspected At: Optima Werkz Pte Ltd (HQ)
10 Ang Mo Kio Industrial Park 2A, #01-05 AMK
Autopoint
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2022)
Parts:	143	TOYOTA COROLLA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNE3041U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Bent	1,335.00 FL	*1,150.00 FL
2	1		*FRONT DOOR INNER TRIM BOARD LH	Mtg Cracked	1,215.00 FL	*980.00 FL
3	1		*REAR DOOR LH	Bent	1,134.00 FL	*1,100.00 FL
4	1		*REAR DOOR INNER TRIM BOARD LH	Serviceable	1,011.00 FL	*- FL
5	1		*REAR DOOR UPPER HINGE LH	Repair	104.00 FL	*- FL
6	1		*REAR DOOR LOWER HINGE LH	Repair	125.00 FL	*- FL
7	1		*REAR DOOR CHECKER LH	Serviceable	194.00 FL	*- FL
8	1		*REAR DOOR REGULATOR LH	Distorted/Jammed	392.00 FL	*392.00 FL
9	1		*SIDE SKIRT LH	Repair	633.00 FL	*- FL
10	1		*FRONT DOOR INNER TRIM CLIPS LH	Necessary	50.00 FS	*50.00 FS
11	1		*REAR DOOR INNER TRIM CLIPS RH	Not Necessary	50.00 FS	*- FS
12	1		*SIDE SKIRT CLIPS LH	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,283.00	3,672.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,535.75	905.50
Total Parts (\$\$)	4,747.25	2,766.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,REPLACE,REFIX,REPAIR & READJUST ACCIDENT AREAS & ETC	New	1,000.00	500.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR LH,REAR DOOR LH,SIDE SKIRT LH,REAR FENDER LH & ETC	New	1,000.00	800.00
3	LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC.TO EFFECT REPLACE OF FRONT DOOR LH	New	120.00	60.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC.TO EFFECT REPLACE OF REAR DOOR LH	New	120.00	60.00
5	TO CHECK WIRING & CENTRAL LOCKING SYSTEM & ETC	New	120.00	20.00
Gross Labour Cost (\$)			2,360.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >