

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002997/APA3Q2**Date:** 17/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0100508151
Claimant Vehicle No :	CB7045D	Insured Vehicle No :	GY3483E
Date of Loss:	31/03/2022	Nature of Claim:	TP
		Claim No:	9332587694SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	CB7045D	Engine No:	6HK1621369
Make & Model:	ISUZU LT134P, 7.8 D (M)	Chassis No:	JALLT134PC7000034
Reg. Date:	14/12/2012 (Man. Year: 2012)	Odometer:	389621 km
Colour:	Maroon		
Engine Capacity:	7790 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,192.93	2,460.00	5,732.93	69.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	1,170.00	2,630.00	69.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,992.93	3,630.00	8,362.93	69.73
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	11,992.93	2,900.00	9,092.93	75.82
+ GST 7.00/7.00% (S\$)	839.51	203.00	636.51	75.82
Nett Amount (S\$)	12,832.44	3,103.00	9,729.44	75.82
+ Loss of Use (5.0 x S\$120.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		38.45		
Nett Liability (S\$)		3,741.45		

INSPECTION

Date of Assignment:	31/03/2022	
Date Inspected:	31/03/2022	Inspected At: Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit Singapore 417921
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Deformed	2,210.00 FS	*1,500.00 FS	
2	1		*REAR BUMPER LOWER DIFFUSER	Cracked	773.67 FS	*400.00 FS	
3	1		*REAR BUMPER ENFORCEMENT	Not Necessary	1,600.00 FL	*- FL	
4	1		*REAR ENGINE COVER	Repair	2,400.00 FL	*- FL	
5	1		*REAR ENGINE COVER HINGES	Not Necessary	600.00 FL	*- FL	
6	1		*REAR ENGINE COVER LOCK	Not Necessary	455.30 FL	*- FL	
7	1		*REAR O/S TAIL LAMP	Cut	812.26 FS	*500.00 FS	
8	1		*REAR 60KM	Necessary	20.00 FS	*10.00 FS	
9	1		*REAR BIZ SAFE 3 STICKER	Necessary	80.00 FS	*50.00 FS	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (\$\$)	8,951.23	2,460.00
					- List Item Discount on L Items 15.00/15.00% (\$\$)	758.30	0.00
					Total Parts (\$\$)	8,192.93	2,460.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PARTS, STRAIGHTEN & WELDING	New	2,000.00	500.00
2	TO SPRAY PAINTING	New	1,400.00	600.00
3	TO REMOVE AND REPLACE REAR TAIL-GATE (MECHANISM)	New	200.00	0.00
4	TO CHECK WIRING	New	100.00	30.00
5	TO RE-SEAL ANTI-RUST	New	100.00	40.00
Gross Labour Cost (\$\$)			3,800.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >